A RESERVE STUDY UPDATE FOR

The Sorrento at the Colony Condominium Association, Inc. Estero, Florida File #22920-06000

FOR PERIOD: January 1, 2022 – December 31, 2022

PREPARED BY
SEDGWICK VALUATION SERVICES
3300 W. LAKE MARY BLVD.
SUITE 350
LAKE MARY, FLORIDA 32746-3405
(800) 248-3376 Ext. 257
(407) 805-0086 Ext. 257



3300 W. Lake Mary Blvd. Suite 350 Lake Mary, FL 32746-3405 T: 800-248-3376 x 257 F: 407-805-9921

Email: service@gabvalue.com On-Line: www.gabvalue.com

December 4, 2021

The Sorrento at the Colony Condominium Association, Inc. Attn: Ms. Bonnie Schinke, Property Manager 23650 Via Venito Estero, Florida 34134

Dear Ms. Schinke,

On January 6, 2012, we completed an initial on-site inspection of The Sorrento at the Colony Condominium Association, Inc.'s common area reserve items. Data gleaned from this inspection was utilized in the completion of an original reserve study report published on June 14, 2012, as well as update reserve study reports published on October 19, 2013 and October 13, 2014. A follow up on-site inspection was completed on July 16, 2015, for use in completion of update reserve study reports published on October 23, 2015, October 28, 2016, January 29, 2018 and August 2, 2018. A follow up on-site inspection was completed on April 9, 2019, for use in completion of update reserve study reports published on June 16, 2019 and September 27, 2020. This reserve study report is an update of that previous reserve study report, which was accepted as accurate and reliable by the association representatives. A Sedgwick Valuation Services representative did not re-inspect the common area reserve items for use in completion of this update reserve study report.

The intent of this report is to show cash reserves necessary for the future repair or replacement of expendable components incorporated into the subject property. The purpose of this report is to aid The Sorrento at the Colony Condominium Association, Inc. in making a determination for cash reserves that are needed to repair or replace short-lived building and/or site components.

The report identifies each component selected, it's estimated useful life, adjusted life, scheduled replacement date, and current cost to repair/replace. The useful and remaining lives of the building components in this study, as well as the current replacement costs, have been selected from market standards, cost estimating services, and consideration of actual recent costs incurred by the association for reserve upgrades. This report is classified as an update reserve study without site visit under the guidelines of the National Reserve Study Standards of the Community Associations Institute, and conforms to the Community Associations Institute Professional Reserve Specialist Code of Ethics. The reserve specialist and Sedgwick Valuation Services have no relationships with the association that would result in actual or perceived conflicts of interest.

This report is our opinion and based upon observed conditions and state of repair. Actual determinations of the current conditions and state of repair for certain items may be beyond the scope of this report. Items may not last as long as projected or may exceed their estimated lives, and actual costs may not correspond to our included estimates. Influences such as weather, catastrophe, improper maintenance, physical abuse, or abnormal use can affect these lives and/or replacement costs. When such occurrences

happen, another inspection should be made and a new revised study prepared. While we have attempted to create a useful tool for the association to plan their needs, the actual reserves set aside are solely at the association's discretion. The findings of this study are not for use in performing an audit, quality/forensic analyses, or background checks of historical records.

In completing this report, the reserve specialist utilized information taken from the prior inspections and reserve study reports. At the association's request and sole discretion, an Engineering Study reserve line item was added. Financial data, including the estimated reserve fund balance as of the analysis date, and property histories, provided by you, were utilized in the completion of this report. This data was not audited, and was assumed to be complete and correct. Unless otherwise specified, the reserve specialist estimated the repair/replacement costs and useful/remaining useful lives taking into account contingencies inherent to this type of work, and the report was prepared utilizing the information gathered in the field and the costs and useful lives estimated by the reserve specialist.

Respectfully submitted, Sedgwick Valuation Services

Stephen F. Brubaker, RS #65 Reserve Specialist, Community Associations Institute



Table of Contents

Project Overview	5
Reserve Study Funding Analysis	
Executive Summary	g
Cash Flow Analysis	
Item Parameter - Category - Chart	
Item Parameters - Detail	
Item Parameters - Full Detail	
Expenditures	78
Cash Flow - Monthly	
Cash Flow - Annual	99
Cash Flow - Chart	
Supplementary Information	
Component Funding Analysis	106
Component Funding Analysis - Categories	
Component Funding Analysis - Items	
Addendum	
Chapter 718 & 719 Florida Statutes	
Terms and Definition	110



PROJECT OVERVIEW



The subject of this reserve study report is the common areas within The Sorrento at the Colony Condominium Association, a 21 story, 72 unit luxury high rise apartment building located with the greater The Colony Golf & Bay club properties in Estero, Florida. Originally constructed in 2001, per the property representatives, the tower building is of heavy concrete frame/superstructure construction, with painted stucco exteriors, fire alarm and sprinkler systems, garage roof mounted recreation decks, and combination flat membrane, pitched tile and pitched metal tile roof covers. The first floor supports an entry porte cochere, grand lobby, galleries/elevator lobbies, mail room, common area parking garages, and typical mechanical, electrical, trash, and storage rooms. The second floor is the amenity level, including an elevator lobby and galleries, administrative offices, social room with bar and residential grade kitchen, billiards room, exercise room, restrooms, two guest suites, a manager's apartment, one dwelling unit, and miscellaneous storage and mechanical rooms. This level also accessed the garage roof recreation decks, which feature paver decks/walkways, and landscaped lawns and planter boxes. Floors 3-21 support the remaining dwelling units, accessed via common area elevator lobbies and hallways. Access to the upper floors is via two traction elevators and two standard stairway cores. The interior finishes are representative of a high quality property, and the common rooms include good quality furnishings/finishes. The exercise room features health club grade fitness equipment. Air conditioning of the common areas is via one roof mounted package unit supporting the hallways and multiple split HVAC air handler/condenser pairs, and there is an inventory of typical exhaust fans. Major mechanical equipment includes the aforementioned elevators and fire safety systems, diesel generator, fire pump, domestic water pumps/equipment, security entry systems, automatic garage

entry/exit gates, water softener system/equipment, and fountain equipment. The building also includes two standard trash chutes and an inventory of trash chute doors.

The common areas include a ground mounted pool and spa, supported by a single story cabana/restroom building, paver decking, perimeter fencing, typical equipment, and better quality deck furniture. Site improvements include marquee signage, asphalt paved and paver parking and drives, concrete curbing/paving, landscaping and irrigation systems, site lighting, decorative entry fountain, and two heavy wood frame parking trellises.

Reserves are only calculated for the replacement of short-lived building or site components. This includes components that require replacement prior to the overall estimated end life of the buildings or structures. Florida statute requires consideration for roofs, exterior paint and/or waterproofing, pavement and all items that have an estimated repair or replacement cost above \$10,000. For the association's consideration, we have included items below the \$10,000 threshold based on their predictability of cost and useful life. This report is designed to provide reasonable, appropriate budgetary cost and useful life data based on market standards for the subject's property type and in compliance with Florida statutes. It was assumed that the unit entry doors, windows, sliding glass doors and balcony decks are the financial responsibility of the unit owners. We are unaware of any private reserve requirements.



RESERVE STUDY FUNDING ANALYSIS

There are two generally accepted means of estimating reserves; the Cash Flow Analysis and the Component Funding Analysis methodologies. The **Cash Flow Analysis** (or Pooling Method) is a method of calculating reserve contributions where contributions to the reserve funds are designed to offset the variable annual expenditures from the reserve fund. This analysis recognizes interest income attributable to reserve accounts over the period of the analysis. Funds from the beginning balances are pooled together and a yearly contribution rate is calculated to arrive at a positive cash flow and reserve account balance to adequately fund the future projected expenditures throughout the period of the analysis.

Prior to December 23, 2002, Florida statute mandated that condominium associations calculate reserves via the Component Funding Analysis method, on an annual basis. Funding at less than 100% of the fully funded estimate, based on the Component Funding Analysis method, could occur only after a full vote of the association membership. As of December 23, 2002, amendments to the Florida Administrative Code recognize the Cash Flow Analysis method as an approved methodology for the calculation of reserve funding for condominium associations. The fund requirement estimated by the Cash Flow Analysis method can now be provided to the membership, on an annual basis as a fully funded figure. The analysis must be completed as a portion of the association's annual budget, include the total estimated useful lives, estimated remaining useful lives, and estimated replacement cost/deferred maintenance expenses of all assets in the reserve budget (minimum roofing, painting, paving and any other item with a replacement/repair cost over \$10,000), and the estimated fund balance of the pooled reserve account as of the beginning of the period for which the budget will be in effect.

If the association maintains a pooled account for reserves, the amount of the contribution to the pooled reserve account as disclosed on the proposed budget shall be not less than that required to ensure that the balance on hand at the beginning of the period for which the budget will go into effect plus the projected annual cash inflows over the remaining estimated useful lives of all of the assets that make up the reserve pool are equal to or greater than the projected annual cash outflows over the remaining estimated useful lives of all of the assets that make up the reserve pool, based on the current reserve analysis. The projected annual cash inflows may include estimated earnings from investment of principal; the association may include annual percentage increases in costs for the reserve components, but these increases are not mandated. Fully funded reserve contributions utilizing this methodology may not include future special assessments, and the annual funding levels cannot include percentage increases.

In our Cash Flow Analysis calculations, we do not include increases in construction costs/inflation. While future costs are expected to be higher than today's costs, which is supported by our analysis of past indexes/trends, increases in costs should be recognized as the association estimates current repair/replacement costs during their annual calculations of full reserve funding. A current cost estimate during the current fiscal year would theoretically be lower than a current cost for future fiscal years. That way the estimates of current cost moving forward will eventually represent current cost as of the date of forecast expenditure. Funding the reserves annually on that basis should ensure that adequate monies are available as of the date of expense, assuming that the current cost estimate is appropriate and that the reserve was fully funded since its last repair/replacement project was completed.

The Component Funding Analysis (or Straight Line Method) calculates the annual contribution amount for each individual line item component by dividing the component's unfunded balance by its



remaining useful life. A component's unfunded balance is its replacement cost less the reserve balance in the component at the beginning of the analysis period. The annual contribution rate for each individual line item component is then summed to calculate the total annual contribution rate for this analysis.

EXECUTIVE SUMMARY

PROPERTY DATA

Property Name: The Sorrento at the Colony

Property Location: Estero, Florida

Property Type: Condominium Association

Total Units: 72

Report Run Date: December 4, 2021

Budget Year Begins: January 1, 2022

Budget Year Ends: December 31, 2022

PROJECTED COMPONENT CATEGORIES AND PARAMETERS

Common Area Interiors
Decks & Planter Boxes
Engineering Study
Mechanical/Electrical
Painting & Waterproofing
Pavement
Pool & Spa
Railings/Screen Enclosures
Roofing
Site Improvements

Total current cost of all reserve components in reserve analysis:	\$ 5,487,693
Estimated beginning reserve fund balance for reserve analysis:	\$ 700,000
Total number of components scheduled for replacement in the 2022 budget year:	1
Total cost of components scheduled for replacement in the 2022 budget year:	\$ 20,000

ANALYSIS RESULTS -CASH FLOW ANALYSIS

Our recommended annual reserve funding contribution amount: \$ 269,400

<u>ANALYSIS RESULTS – COMPONENT FUNDING ANALYSIS</u>

Our recommended annual reserve funding contribution amount: \$ 1,022,019

CONCLUSIONS

Based on the Cash Flow Analysis methodology, the association can fully fund the reserves as analyzed in this report at \$269,400 in fiscal year 2022. In this analysis we have utilized a 0.65% rate of return on reserve funds invested over the study period (assuming safe investment in CDs, money market accounts, etc.). The Cash Flow Analysis utilizes a pooling effect with reserve funds by pooling all funds together and distributing these funds to individual components as their replacement comes due. Funds that are pooled together in the cash flow analysis include the beginning balance, contributions to the reserve funds and interest earned on reserve funds. These pooled funds are matched against reserve expenditures throughout the period of the analysis by using our reserve analysis software program to ensure that the available funds are always greater than expenditures. Based on our Component Funding Analysis model, the reserves as analyzed in this report suggest that in order to fully fund in fiscal year 2022, the contribution should be \$1,022,019. The Component Funding Analysis is a straight-line accounting procedure that was previously mandated by the State of Florida. Until December 2002, funding at less




than this amount was considered partial funding by the state and required approval by the association members. As stated previously in this report, changes to the administrative code now allow the implementation/use of a pooling, or cash flow method of reserve analysis.

CASH FLOW ANALYSIS



Analysis Date - January 1, 2022

Item Parameter - Category - Chart



PRN:10/23/2021 Page 12 of 122

Analysis Date - January 1, 2022 Item Parameters - Detail

Category Reserve Item	Service Date	Replace Date	Basis Cost	Quantity	Current Cost	Est Life	Adj Life	Rem Life	Future Cost
Common Area Interiors									
Admin. Offices Furnishings/Finishes	06/01/2018	06/01/2035	\$ 5,740.00	2 stations	\$ 11,480.00	17:00	17:00	13:05	\$ 11,480.00
Billiards Room Furnishings/Finishes	06/01/2001	01/01/2025	51.10	320 sq ft	16,352.00	20:00	23:07	3:00	16,352.00
Elevator Cab Interiors	07/01/2021	07/01/2041	20,750.00	2 cabs	41,500.00	20:00	20:00	19:06	41,500.00
Fitness Room Flooring	08/01/2018	08/01/2033	13.72	630 sq ft	8,643.60	15:00	15:00	11:07	8,643.60
Fitness Room Strength Stations/Equip.	06/01/2001	01/01/2025	4,188.00	7 stations	29,316.00	15:00	23:07	3:00	29,316.00
Guest Suites Furnishings/Finishes	01/01/2013	09/01/2023	18,950.00	2 suites	37,900.00	10:00	10:08	1:08	37,900.00
Guest Suites Restrooms	10/01/2019	10/01/2039	132.35	130 sq ft	17,205.50	20:00	20:00	17:09	17,205.50
Hallways Carpeting	09/01/2016	09/01/2023	88.83	1,874 sq yds	166,467.42	14:00	7:00	1:08	166,467.42
Hallways Furnishings/Finishes	09/01/2015	09/01/2029	14.00	16,700 sq ft	233,800.00	14:00	14:00	7:08	233,800.00
Lobby/Galleries Furnishings	10/01/2016	10/01/2031	20.35	4,640 sq ft	94,424.00	15:00	15:00	9:09	94,424.00
Lobby/Galleries Restrooms	05/01/2019	05/01/2039	140.25	330 sq ft	46,282.50	20:00	20:00	17:04	46,282.50
Lobby/Galleries Wall/Door Finishes	10/01/2016	10/01/2031	3.43	7,600 sq ft	26,068.00	15:00	15:00	9:09	26,068.00
Social Room Bar/Kitchen	06/01/2001	09/01/2023	295.45	220 sq ft	64,999.00	20:00	22:03	1:08	64,999.00
Social Room Carpeting	10/01/2013	09/01/2023	88.10	111 sq yds	9,779.10	10:00	9:11	1:08	9,779.10
Social Room Furnishings/Finishes	10/01/2013	10/01/2027	61.80	970 sq ft	59,946.00	14:00	14:00	5:09	59,946.00
					864,163.12			_	864,163.12
Decks & Planter Boxes									
Lawns/Landscaping Waterproofing	06/01/2001	06/01/2033	\$ 44.25	19,000 sq ft	\$ 840,750.00	25:00	32:00	11:05	\$ 840,750.00
Pavers/Waterproofing	06/01/2001	06/01/2033	40.15	8,600 sq ft	345,290.00	25:00	32:00	11:05	345,290.00
Planter Boxes Waterproofing	10/01/2016	10/01/2046	106.40	1,900 sq ft	202,160.00	25:00	30:00	24:09	202,160.00
					1,388,200.00			_	1,388,200.00
Engineering Study									
Engineering Study	06/01/2015	06/01/2022	\$ 20,000.00	1 lp sm	\$ 20,000.00	7:00	7:00	0:05	\$ 20,000.00
,				·	20,000.00			_	20,000.00
Mechanical/Electrical									
Domestic Water Pumps/Equipment	10/01/2015	10/01/2039	\$ 647.55	75 hp	\$ 48,566.25	24:00	24:00	17:09	\$ 48,566.25
Elevator Mechanical Modernization	07/01/2021	07/01/2051	292,405.00	2 cabs	584,810.00	30:00	30:00	29:06	584,810.00
Exhaust/Pressurization Fans	06/01/2001	06/01/2031	2,519.00	20 each	50,380.00	30:00	30:00	9:05	50,380.00

Analysis Date - January 1, 2022 Item Parameters - Detail

Category Reserve Item	Service Date	Replace Date	Basis Cost	Quantity	Current Cost	Est Life	Adj Life	Rem Life	Future Cost
Mechanical/Electrical									
Fire Alarm System Modernization	06/01/2020	06/01/2045	\$ 3,765.00	76 units	\$ 286,140.00	25:00	25:00	23:05	\$ 286,140.00
Fire Pump/Equipment	06/01/2001	06/01/2046	79,420.00	1 lp sm	79,420.00	45:00	45:00	24:05	79,420.00
Garage Gate/Equipment North	05/01/2016	05/01/2030	17,880.00	1 lp sm	17,880.00	14:00	14:00	8:04	17,880.00
Garage Gate/Equipment South	07/01/2021	07/01/2035	17,880.00	1 lp sm	17,880.00	14:00	14:00	13:06	17,880.00
Generator/Equipment	06/01/2001	06/01/2041	484.75	200 kW	96,950.00	40:00	40:00	19:05	96,950.00
Hallways Outside Air Unit	08/01/2016	08/01/2028	2,849.70	40 tons	113,988.00	12:00	12:00	6:07	113,988.00
Video Surveillance System	10/01/2019	10/01/2030	1,344.00	12 cameras	16,128.00	11:00	11:00	8:09	16,128.00
Water Softener System/Equipment	06/01/2021	01/01/2032	17,000.00	1 lp sm	17,000.00	10:00	10:07	10:00	17,000.00
					1,329,142.25				1,329,142.25
Painting & Waterproofing									
Paint Garage Ceilings/Piping	06/01/2001	09/01/2027	\$ 0.83	42,000 sq ft	\$ 34,860.00	20:00	26:03	5:08	\$ 34,860.00
Paint Garage Walls/Doors	08/01/2019	08/01/2037	0.54	42,000 sq ft	22,680.00	18:00	18:00	15:07	22,680.00
Paint Stairway Interiors	06/01/2001	09/01/2023	882.25	42 flights	37,054.50	20:00	22:03	1:08	37,054.50
Paint/Waterproof Building Exteriors	07/01/2016	07/01/2023	4,697.00	72 units	338,184.00	7:00	7:00	1:06	338,184.00
					432,778.50				432,778.50
Pavement									
Asphalt Paving (Replacement)	06/01/2001	09/01/2027	\$ 15.59	3,760 sq yds	\$ 58,618.40	20:00	26:03	5:08	\$ 58,618.40
Asphalt Paving (Sealcoat/Rejuvenation) 2023	06/01/2001	06/01/2023	1.97	3,760 sq yds	7,407.20	3:00	3:00	1:05	7,407.20
Asphalt Paving (Sealcoat/Rejuvenation) 2030	06/01/2001	06/01/2030	1.97	3,760 sq yds	7,407.20	3:00	8:05	8:05	7,407.20
Asphalt Paving (Sealcoat/Rejuvenation) 2033	06/01/2001	06/01/2033	1.97	3,760 sq yds	7,407.20	3:00	11:05	11:05	7,407.20
Asphalt Paving (Sealcoat/Rejuvenation) 2036	06/01/2001	06/01/2036	1.97	3,760 sq yds	7,407.20	3:00	14:05	14:05	7,407.20
Asphalt Paving (Sealcoat/Rejuvenation) 2039	06/01/2001	06/01/2039	1.97	3,760 sq yds	7,407.20	3:00	17:05	17:05	7,407.20
Asphalt Paving (Sealcoat/Rejuvenation) 2042	06/01/2001	06/01/2042	1.97	3,760 sq yds	7,407.20	3:00	20:05	20:05	7,407.20
Asphalt Paving (Sealcoat/Rejuvenation) 2045	06/01/2001	06/01/2045	1.97	3,760 sq yds	7,407.20	3:00	23:05	23:05	7,407.20
Drives/Parking Pavers	06/01/2001	09/01/2027	6.66	8,200 sq ft	54,612.00	25:00	26:03	5:08	54,612.00
					165,080.80				165,080.80
Pool & Spa									
Deck Furniture	10/01/2021	10/01/2033	\$ 415.40	65 pieces	\$ 27,001.00	12:00	12:00	11:09	\$ 27,001.00
Decking	06/01/2001	06/01/2027	6.66	5,830 sq ft	38,827.80	25:00	26:00	5:05	38,827.80
Fencing/Gates	06/01/2001	06/01/2027	59.43	348 In ft	20,681.64	24:00	26:00	5:05	20,681.64
Heater 1	06/01/2019	06/01/2034	7,826.00	1 each	7,826.00	15:00	15:00	12:05	7,826.00

Analysis Date - January 1, 2022 Item Parameters - Detail

Category Reserve Item	Service Date	Replace Date	Basis Cost	Quantity	Current Cost	Est Life	Adj Life	Rem Life	Future Cost
Heater 2	06/01/2013	06/01/2028	7,826.00	1 each	7,826.00	15:00	15:00	6:05	7,826.00
Heater 3	06/01/2021	06/01/2036	7,826.00	1 each	7,826.00	15:00	15:00	14:05	7,826.00
Heater 4	06/01/2021	06/01/2036	7,826.00	1 each	7,826.00	15:00	15:00	14:05	7,826.00
Interiors Resurfacing	08/23/2012	08/01/2024	18.10	1,350 sq ft	24,435.00	10:00	12:00	2:07	24,435.00
Summer Kitchen	01/01/2015	01/01/2029	9,550.00	1 lp sm	9,550.00	14:00	14:00	7:00	9,550.00
					151,799.44			-	151,799.44
Railings/Screen Enclosures									
Decktop Railings	06/01/2001	06/01/2031	\$ 73.53	520 In ft	\$ 38,235.60	30:00	30:00	9:05	\$ 38,235.60
Garage Screen Enclosures	06/01/2014	06/01/2039	11.13	2,560 sq ft	28,492.80	25:00	25:00	17:05	28,492.80
Units Railings/Screen Enclosures/Doors	06/01/2014	06/01/2039	242,307.00	1 lp sm	242,307.00	25:00	25:00	17:05	242,307.00
Units Screening Replacement	06/01/2014	12/01/2026	595.00	120 lanais	71,400.00	12:06	12:06	4:11	71,400.00
					380,435.40			-	380,435.40
Roofing									
Mechanical Building Roofing	06/01/2001	06/01/2027	\$ 1,528.00	10.65 sqs	\$ 16,273.20	26:00	26:00	5:05	\$ 16,273.20
Pool Pavilion Roofing	06/01/2001	06/01/2027	1,528.00	7 sqs	10,696.00	26:00	26:00	5:05	10,696.00
Porte Cochere Roofing	06/01/2001	06/01/2027	1,528.00	20.3 sqs	31,018.40	26:00	26:00	5:05	31,018.40
Tower Roofing (Flat)	06/01/2001	10/01/2024	3,281.50	88 sqs	288,772.00	20:00	23:04	2:09	288,772.00
Tower Roofing (Metal Shingle)	06/01/2001	06/01/2036	4,566.70	56.5 sqs	258,018.55	35:00	35:00	14:05	258,018.55
					604,778.15			_	604,778.15
Site Improvements									
Signage Allowance	06/01/2001	01/01/2027	10,000.00	1 lp sm	10,000.00	20:00	25:07	5:00	10,000.00
Site Lighting	06/01/2001	06/01/2025	76,685.00	1 lp sm	76,685.00	24:00	24:00	3:05	76,685.00
Trellises	10/01/2013	10/01/2027	29.32	1,800 sq ft	52,776.00	14:00	14:00	5:09	52,776.00
West/Nature Preserve Fencing	01/01/2015	01/01/2039	11,855.00	1 lp sm	11,855.00	24:00	24:00	17:00	11,855.00
					151,316.00			_	151,316.00
					5,487,693.66			=	5,487,693.66

Analysis Date - January 1, 2022
Item Parameters - Full Detail

Admin. Offices Furnishings/Finishes

Item Numb	Item Number 15			Me	asurement Basis		stations	
Туре		Common Are	a		Esti	mated Useful Life		17 Years
Category		Common Are	a Interiors		Bas	sis Cost		5,740.00
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0015		06/01/2018	06/01/2035	13:05	17:00	2	11,480.00	11,480.00
							11,480.00	11,480.00
Comments								

It is our market observation that while minor additions/replacements can be necessary from time to time, major administrative office furnishings/finishes projects (including, but not necessarily limited to, wall and door finishes, tables, chairs, desks, bookcases/shelving, window treatments, decorative lighting/lamps, wall art, plants, etc.) can be expected on a 15-20 year life cycle. Administrative offices furnishings replacement/upgrades was reportedly completed in 2018, and a 2035 expense date scheduled accordingly.



At the association's request and sole discretion, replacement of the carpeting in these common areas was excluded from this report. We estimate a current replacement cost of cost of \$3,300, based on the approximate floor area.

PRN:10/23/2021 Page 16 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Billiards Room Furnishings/Finishes

Item Number	tem Number 16			Me	easurement Basis		sq ft
Туре	Common Are	а		Est	imated Useful Life		20 Years
Category	Common Are	a Interiors		Bas	sis Cost		51.10
Tracking	Logistical			Sal	vage Value		\$ 0.00
Method	Adjusted						
	Service	Replace	Rem	Adj		Current	Future
Code Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0016	06/01/2001	01/01/2025	3:00	23:07	320	16,352.00	16,352.00
						16,352.00	16,352.00
Comments							

Recognizing that minor additions/replacements/upgrades will be necessary from time to time, life cycles ranging from roughly 10 to 20 years have been observed for major furnishings upgrades in primary common areas (hallways, social rooms, lobbies, etc.) at properties of similar overall quality. These upgrades include, but at not necessarily limited to, wall and door finishes, sofas and chairs, tables, armoires, area rugs, window treatments, wall art/mirrors, plants, billiards tables, decorative lighting/lamps, ceiling fans, etc. At the association's prior request and sole discretion, furnishings/finishes upgrades in the billiards room was forecast in 2025; a recurring 20 year life cycle was forecast thereafter.



At the association's request and sole discretion, replacement of the billiard room carpeting was excluded from this report. We estimate a current replacement cost of cost of \$3,440, based on the approximate floor area.

PRN:10/23/2021 Page 17 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Elevator Cab Interiors

Item Num	ber	21			Me	asurement Basis		cabs
Туре	/pe Common Area			Estimated Useful Life			20 Years	
Category	tegory Common Area Interiors		Bas	Basis Cost				
Tracking		Logistical			Salvage Value			\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-002	1	07/01/2021	07/01/2041	19:06	20:00	2	41,500.00	41,500.00
							41,500.00	41,500.00
Comment	s							

A line item has also been included for eventual major interior refurbishment/renovation of the elevator cabs, including flooring systems, walls, ceilings and lighting, etc. In better quality properties like the subject, this upgrade is completed on a maximum 20 year schedule. The current per cab cost estimate is based solely on actual costs incurred during the 2021 project, as reported by the association.

PRN:10/23/2021 Page 18 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Fitness Room Flooring

Item Number	4			Me	asurement Basis		sq ft
Туре	Common	Area		Esti	imated Useful Life		15 Years
Category	Common	Area Interiors		Bas	Basis Cost		
Tracking	Logistical			Sal	vage Value		\$ 0.00
Method	Fixed						
	Servic	e Replace	Rem	Adj		Current	Future
Code Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0004	08/01/20	08/01/2033	11:07	15:00	630	8,643.60	8,643.60
						8,643.60	8,643.60
Comments							

The association expects to complete replacement of the fitness room flooring in summer 2018, installing a more durable/longer lasting rubberized flooring. This type of flooring has a market observed life cycle in the low to mid 10 year range. Based on the reported 15 year warranty purchased with the existing flooring, this replacement was scheduled again in 2033. The floor area is a rounded estimate.



PRN:10/23/2021 Page 19 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Fitness Room Strength Stations/Equip.

Item Numbe	er	12			Me	easurement Basis		stations
Туре		Common Are	a		Esti	imated Useful Life		15 Years
Category		Common Are	area Interiors			sis Cost		4,188.00
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0012		06/01/2001	01/01/2025	3:00	23:07	7	29,316.00	29,316.00
							29,316.00	29,316.00
Comments								

To ensure that modern, appealing exercise equipment is in use, data gleaned from similar properties reflects a typical useful life in the mid-10 year range for replacement of strength training stations/equipment. The existing inventory is original to 2001, reflecting an actual age of \pm 0 years; as such, the market suggests that replacements should be expected in the near future. At the association's prior request and sole discretion, a 2025 inventory replacement date was scheduled. This reflects a budgetary useful life of \pm 0 years, which is well beyond observed market norms and will likely result in less desirable equipment in use.



PRN:10/23/2021 Page 20 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Guest Suites Furnishings/Finishes

Item Numbe	er	22			Me	easurement Basis		suites
Туре		Common Are	a		Estimated Useful Life			10 Years
Category Common Area Interiors		a Interiors		Bas	sis Cost		18,950.00	
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0022		01/01/2013	09/01/2023	1:08	10:08	2	37,900.00	37,900.00
							37,900.00	37,900.00
Comments								

This category refers to costs associated with major interior renovation of the guest suites, including short lived carpet replacement, wall finishes, furnishings, etc. Due to the more transient nature of the use of guest suites, large expenses associated with interior renovation are generally incurred on a \pm 10 year basis. This expense was forecast in 2023 accordingly. The current per suite cost estimate is an average figure, based on the total square footages.



The interior furnishings/finishes within the manager's unit are reportedly the financial responsibility of the manager, and were therefore omitted from this report.

PRN:10/23/2021 Page 21 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Guest Suites Restrooms

Item Numb	tem Number 72				Me	asurement Basis		sq ft
Туре		Common Are	a		Est	imated Useful Life		20 Years
Category		Common Are	a Interiors		Bas	sis Cost		132.35
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0072		10/01/2019	10/01/2039	17:09	20:00	130	17,205.50	17,205.50
							17,205.50	17,205.50
Comments	;							

The association completed renovation of the restrooms in the guest suites in 2019; at some point this expense should be expected again. Life cycles of less than 15 years, to 30+ years, have been observed in properties of similar quality. A 20 year life cycle estimate reflects a 2039 expense date. The current cost estimate does not include any unforeseen floor area reconfiguration(s) and/or expansion(s).



PRN:10/23/2021 Page 22 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Hallways Carpeting

Item Number	5			Measurement Basis			sq yds
Type Common Area			Estimated Useful Life			14 Years	
Category	egory Common Area Interiors Basis Cost		sis Cost		88.83		
Tracking	Logistical			Sal	vage Value		\$ 0.00
Method	Adjusted						
	Service	Replace	Rem	Adj		Current	Future
Code Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0005	09/01/2016	09/01/2023	1:08	7:00	1,874	166,467.42	166,467.42
						166,467.42	166,467.42
Comments							

Replacement of the carpeting in the common area hallways was forecast on a recurring 14 year life cycle, to be completed concurrently with scheduled furnishings/finishes upgrades, suggesting this expense again in 2029. At the association's request and sole discretion, the remaining useful life was adjusted to reflect a 2023 expense date. The current cost estimate includes removal and disposal of the existing carpeting and installation with like quality. The floor area estimate includes a typical market waste allowance.



PRN:10/23/2021 Page 23 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Hallways Furnishings/Finishes

Item Numbe	er	73			Me	asurement Basis		sq ft
Туре		Common Are	a		Esti	Estimated Useful Life		14 Years
Category		Common Are	a Interiors		Bas	sis Cost		14.00
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0073		09/01/2015	09/01/2029	7:08	14:00	16,700	233,800.00	233,800.00
							233,800.00	233,800.00
Comments								

Recognizing that minor additions/replacements/upgrades will be necessary from time to time, life cycles ranging from roughly 10 to 20 years have been observed for major furnishings upgrades in primary common areas (hallways, social rooms, lobbies, etc.) at properties of similar overall quality. These upgrades include, but at not necessarily limited to, wall and door finishes, sofas and chairs, tables, armoires, area rugs, window treatments, wall art/mirrors, plants, billiards tables, decorative lighting/lamps, ceiling fans, etc. The 2015 hallway renovation project included furnishings/finishes upgrades, and this expense was scheduled again in 2029 accordingly.





PRN:10/23/2021 Page 24 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Lobby/Galleries Furnishings

Item Numbe	er	17			Me	easurement Basis		sq ft
Туре		Common Area	a		Est	imated Useful Life		15 Years
Category		Common Area	a Interiors		Basis Cost			20.35
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0017		10/01/2016	10/01/2031	9:09	15:00	4,640	94,424.00	94,424.00
							94,424.00	94,424.00
Comments								

Recognizing that minor additions/replacements/upgrades will be necessary from time to time, life cycles ranging from roughly 10 to 20 years have been observed for major furnishings upgrades in primary common areas (hallways, social rooms, lobbies, etc.) at properties of similar overall quality. These upgrades include, but at not necessarily limited to, wall and door finishes, sofas and chairs, tables, armoires, area rugs, window treatments, wall art/mirrors, plants, billiards tables, decorative lighting/lamps, ceiling fans, etc. Based on the fall 2016 lobby/galleries furnishings project, which reflects an actual useful life of +/- 15 years, a 2031 expense date was scheduled.







PRN:10/23/2021 Page 25 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Lobby/Galleries Restrooms

Item Numb	er	24			Me	easurement Basis		sq ft
Туре		Common Are	a		Est	imated Useful Life		20 Years
Category		Common Are	a Interiors		Basis Cost		140.	
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0024		05/01/2019	05/01/2039	17:04	20:00	330	46,282.50	46,282.50
							46,282.50	46,282.50
Comments	;							

The association completed renovation of the lobby restrooms in 2019; at some point this expense should be expected again. Life cycles of less than 15 years, to 30+ years, have been observed in properties of similar quality. A 20 year life cycle estimate reflects a 2039 expense date. The current cost estimate does not include any unforeseen floor area reconfiguration(s) and/or expansion(s).



PRN:10/23/2021 Page 26 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Lobby/Galleries Wall/Door Finishes

Item Numbe	er	28			Me		sq ft	
Туре		Common Area	a		Estimated Useful Life			15 Years
Category Commo		Common Area	ommon Area Interiors			sis Cost		3.43
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0028		10/01/2016	10/01/2031	9:09	15:00	7,600	26,068.00	26,068.00
							26,068.00	26,068.00
Comments								

Life cycles of less than 10 years, to +/- 15 years, have been observed for third party painting/wall refinishing in properties of similar overall quality; the useful life assumes a routine in house touch up and repair schedule, as a function of general maintenance. A 15 year life cycle and 2031 expense date were forecast for wall/door refinishing in the common area lobby/galleries. The wall/door area is a rounded estimate.





PRN:10/23/2021 Page 27 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Social Room Bar/Kitchen

Item Number 20				Measurement Basis			sq ft	
Type Common Area			Estimated Useful Life			20 Years		
Category Common Area Interiors Basi		Basis Cost		295.45				
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0020		06/01/2001	09/01/2023	1:08	22:03	220	64,999.00	64,999.00
							64,999.00	64,999.00
Comments								

This fund is designed to provide monies for eventual major interior refurbishment of the bar and kitchen in the lobby level social room, including (but not necessarily limited to), tile/marble flooring, cabinetry and/or counters, plumbing and electrical fixtures, etc. The current cost estimate is based on our experience with interior renovation of this type and the included floor areas. At the association's request and sole discretion, this expense was forecast in 2023. The current cost estimate was included at the association's request and sole discretion (expected \$65,000, including appliances).





PRN:10/23/2021 Page 28 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Social Room Carpeting

Item Numbe	r	6			Me	easurement Basis		sq yds
Туре		Common Area	a		Estimated Useful Life			10 Years
Category Common Area Interiors		a Interiors		Basis Cost			88.10	
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0006		10/01/2013	09/01/2023	1:08	9:11	111	9,779.10	9,779.10
							9,779.10	9,779.10
Comments								

We have observed life cycles ranging from as low as 5-6 years, to 15+ years for replacement of common area carpeting in properties of similar quality. The useful life typically depends on the amount of usage, as well as level of ongoing maintenance and association cosmetic tastes; at the association's request and sole discretion, this expense was forecast again in 2023. A recurring 10 year life cycle was scheduled thereafter. The floor area estimate includes a typical market waste allowance.



PRN:10/23/2021 Page 29 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Social Room Furnishings/Finishes

Item Numb	er	19			Me	easurement Basis		sq ft	
Туре		Common Are	a		Estimated Useful Life			14 Years	
Category		Common Are	a Interiors		Basis Cost			61.80	
Tracking		Logistical			Sal	vage Value		\$ 0.00	
Method		Fixed							
		Service	Replace	Rem	Adj		Current	Future	
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost	
910-000-0019		10/01/2013	10/01/2027	5:09	14:00	970	59,946.00	59,946.00	
							59,946.00	59,946.00	
Comments									

Recognizing that minor additions/replacements/upgrades will be necessary from time to time, life cycles ranging from roughly 10 to 20 years have been observed for major furnishings upgrades in primary common areas (hallways, social rooms, lobbies, etc.) at properties of similar overall quality. These upgrades include, but at not necessarily limited to, wall and door finishes, sofas and chairs, tables, armoires, area rugs, window treatments, wall art/mirrors, plants, billiards tables, decorative lighting/lamps, ceiling fans, etc. The association expects to complete this project in 2027, which is reflective of a +/- 14 year life cycle. The current cost estimate does not reflect any unforeseen floor area reconfiguration(s) and/or expansion(s).



PRN:10/23/2021 Page 30 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Lawns/Landscaping Waterproofing

Item Number	128			Measurement Basis			sq ft
Туре	ype Common Area			Estimated Useful Life			25 Years
Category Decks & Planter Boxes Basis		Basis Cost		44.25			
Tracking	Logistical			Sal	vage Value		\$ 0.00
Method	Adjusted						
	Service	Replace	Rem	Adj		Current	Future
Code Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0128	06/01/2001	06/01/2033	11:05	32:00	19,000	840,750.00	840,750.00
					_	840,750.00	840,750.00

Comments

Without proper waterproofing, moisture intrusion can occur into the underlying concrete systems, which can cause premature deterioration of those systems and the need for costly concrete restoration. It has been our experience that major deck restoration is typically necessary on a +/- 25 year schedule, although we have observed life cycles of +/- 5 years higher or lower than that age. This fund is designed to provide monies for restoration of the garage roof deck mounted lawns/landscaping, including removal of all landscaping and soils, restoration/replacement of the underlying waterproofing systems/expansion joints, drainage and electrical upgrades, etc. and installation of new soils and landscaping. The total area is a rounded estimate. At the association's request and sole discretion, the remaining useful life was adjusted to reflect a 2033 expense date; this reflects an expected useful life of 32 years, which is beyond the typical life cycle observed for this project and may result in higher maintenance and/or restoration costs. As such, the funding estimates put forth in this report do not reflect our opinion of full statutory reserve funding.



Costs and time frames can vary, sometimes widely, from property to property. We recommend that prior to reserve funding decisions are made, and on a periodic and

PRN:10/23/2021 Page 31 of 122

Analysis Date - January 1, 2022

regular basis thereafter, a qualified structural/waterproofing consultant(s) assess these systems to determine more specific cost and remaining useful life parameters. We reserve the right to modify this report upon receipt of such an assessment(s).

PRN:10/23/2021 Page 32 of 122

Analysis Date - January 1, 2022 Item Parameters - Full Detail

Pavers/Waterproofing	/aterproofing
----------------------	---------------

Item Number	33			Me	asurement Basis		sq ft
Туре	Common Area			Estimated Useful Life			25 Years
Category	Decks & Plant		Basis Cost			40.15	
Tracking	Logistical			Salv	vage Value		\$ 0.00
Method	Adjusted						
	Service	Replace	Rem	Adj		Current	Future
Code Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0033	06/01/2001	06/01/2031	9:05	30:00	8,600	345,290.00	345,290.00
						345,290.00	345,290.00

Without proper waterproofing, moisture intrusion can occur into the underlying concrete systems, which can cause premature deterioration of those systems and the need for costly concrete restoration. It has been our experience that major deck restoration is typically necessary on a +/- 25 year schedule, although we have observed life cycles of +/- 5 years higher or lower than that age. This fund is designed to provide monies for restoration of the drives, parking areas, and walkways having paver decking, located over the ground level parking garage over an association requested (included at association's sole discretion) 30 year life cycle. This upgrade typically includes removal of the existing paver decking, restoration/replacement of the underlying waterproof membranes and expansion joints, some measure of incidental concrete restoration, and replacement of the paver decking. The total area is a rounded estimate.





Costs and time frames can vary, sometimes widely, from property to property. We recommend that prior to reserve funding decisions are made, and on a periodic and regular basis thereafter, a qualified structural/waterproofing consultant(s) assess these systems to determine more specific cost and remaining useful life parameters. We reserve the right to modify this report upon receipt of such an assessment(s).

PRN:10/23/2021 Page 33 of 122

Analysis Date - January 1, 2022 Item Parameters - Full Detail

Planter Bo	oxes Water	proofing
------------	------------	----------

Item Number Type Category		127	127			easurement Basis		sq fi	
		Common Area	a		Esti	Estimated Useful Life			
		Decks & Plant	ter Boxes		Bas	sis Cost		106.40	
Tracking		Logistical		Sal	vage Value		\$ 0.00		
Method		Adjusted							
		Service	Replace	Rem	Adj		Current	Future	
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost	
910-000-0127		10/01/2016	10/01/2046	24:09	30:00	1,900	202,160.00	202,160.00	
							202,160.00	202,160.00	
Comments									

Without proper waterproofing, moisture intrusion can occur into the underlying concrete systems, which can cause premature deterioration of those systems and the need for costly concrete restoration. It has been our experience that major deck restoration is typically necessary on a +/- 25 year schedule, although we have observed life cycles of +/- 5 years higher or lower than that age. This fund is designed to provide monies for restoration over an association requested (included at association's sole discretion) 30 year life cycle. The current cost estimate includes removal of all landscaping and soils, restoration/replacement of the interior waterproofing systems/expansion joints, drainage and electrical upgrades, etc. and installation of new soils and landscaping. The total area is a rounded estimate.



Costs and time frames can vary, sometimes widely, from property to property. We recommend that prior to reserve funding decisions are made, and on a periodic and regular basis thereafter, a qualified structural/waterproofing consultant(s) assess these systems to determine more specific cost and remaining useful life parameters. We reserve the right to modify this report upon receipt of such an assessment(s).

PRN:10/23/2021 Page 34 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Ė	nį	zır	ıe	er	'n	g	S	tu	d	y	

Item Number	136			Me	asurement Basis	lp sm 7 Years 20,000.00	
Туре	Common Are	a		Esti	mated Useful Life		
Category	Engineering S	tudy		Bas	sis Cost		
Tracking	Logistical		Salvage Value				\$ 0.00
Method	Fixed						
	Service	Replace	Rem	Adj		Current	Future
Code Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0136	06/01/2015	06/01/2022	0:05	7:00	1	20,000.00	20,000.00
						20,000.00	20,000.00

At the association's request and sole discretion, a \$20,000 expense was scheduled in 2022 and on a recurring 7 year life cycle for engineering analyses.

PRN:10/23/2021 Page 35 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Insurance	Reserve
-----------	---------

Item Number		129			Me	Measurement Basis				
Туре		Common Area				Estimated Useful Life				
		Common Are	a		ESU	0 Year				
Category	,	Insurance Re	serve		Basis Cost			0.00		
Tracking		Logistical		Salvage Value			\$ 0.00			
Method		Fixed								
		Service	Replace	Rem	Adj		Current	Future		
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost		
910-000-01	.29		06/01/2001	0:00	0:00	0	0.00	0.00		
Commer	nts									

Some associations establish and fund non-statutory reserves to provide funds for the possibility of financial losses due to hurricane/storm damage and/or insurance deductibles. Unlike say painting or roof replacement, there is no market standard for this type of reserve; some associations choose to reserve very aggressively, while others more conservatively. On that basis, we include this type of reserve only when provided an association's funding goal in total dollars and time frame in which to reach that goal. At such time as the association provides a budgetary insurance reserve funding goal and time frame in which to reach that goal, this report can be amended to include this component.

PRN:10/23/2021 Page 36 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Domestic Water Pumps/Equipment

Item Number	36			Me	asurement Basis		hp
Туре	Common Area	a		Esti	mated Useful Life		24 Years
Category	Mechanical/E	lectrical		Bas	is Cost		647.55
Tracking	Logistical			Salv	vage Value		\$ 0.00
Method	Fixed						
	Service	Replace	Rem	Adj		Current	Future
Code Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0036	10/01/2015	10/01/2039	17:09	24:00	75	48,566.25	48,566.25
						48,566.25	48,566.25

The common area mechanical equipment inventory includes a typical domestic water pump and controller system, with two 30 HP and one 15 HP pumps. While pump rebuilds, motor rewinds, etc. will be necessary as a portion of the typical maintenance program, the market indicates that major modernization/replacement of these systems will be necessary on a life cycle in the low to mid 20 year range. This fund is designed to provide monies for as needed repairs to and eventual modernization/replacement of this equipment over a 24 year life cycle, accordingly.



PRN:10/23/2021 Page 37 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Elevator Mechanical Modernization

Item Numb	er	37			Me	asurement Basis		cabs
Туре		Common Area	a		Esti	mated Useful Life		30 Years
Category		Mechanical/E	lectrical		Bas	sis Cost		292,405.00
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0037		07/01/2021	07/01/2051	29:06	30:00	2	584,810.00	584,810.00
							584,810.00	584,810.00
Comments								

Modernization of traction elevator mechanical and electrical components, including (but not necessarily limited to), controllers, door hardware, etc. has been observed on life cycles in the 25-30 year range in properties of similar quality, assuming a typical maintenance program. This expense was forecast again in 2051, accordingly. As this project was completed since our most recent inspection, no photograph was included.

PRN:10/23/2021 Page 38 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Exhaust/Pressurization Fans

Item Number	50			М	easurement Basis		each
Туре	Common Area	a		Es	timated Useful Life		30 Years
Category	Mechanical/E	lectrical		Ва	sis Cost		2,519.00
Tracking	Logistical			Sa	lvage Value		\$ 0.00
Method	Fixed						
	Service	Replace	Rem	Adj		Current	Future
Code Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0050	06/01/2001	06/01/2031	9:05	30:00	20	50,380.00	50,380.00
						50,380.00	50,380.00
Comments							

None of the individual common area exhaust/pressurization fans has a current repair/replacement cost of \$10,000+, so their inclusion in the association's estimate of full statutory reserve funding for fiscal year 2022 is not mandated under current Florida Statute 718 requirements. Some associations prefer to fund as needed repair/replacement projects through their annual operating budgets, as a function of routine maintenance. Others do establish and fund reserves for repairs/replacements, given the higher aggregate inventory replacement cost. For the association's consideration, we have included a reserve for the common area exhaust/pressurization fans.

Data gleaned from properties of similar design both within and outside the local market area indicates that while some units may last longer than others, replacement of typical inventories of common area exhaust/pressurization fans is necessary on a 20-30 year life cycle (assuming non-corrosive design/construction). This fund is designed to provide monies for as needed repairs/replacements of the existing fans over a 30 year life cycle. The current unit cost estimate is an average figure, given the differing types and sizes of fans in use. The photograph is of a representative fan.



PRN:10/23/2021 Page 39 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Fire Alarm System Modernization

Item Numb	er	38			Me	easurement Basis		units
Туре		Common Area	a		Est	imated Useful Life		25 Years
Category		Mechanical/E	lectrical		Bas	sis Cost		3,765.00
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0038		06/01/2020	06/01/2045	23:05	25:00	76	286,140.00	286,140.00
							286,140.00	286,140.00
Comments								

Due to improvements in technology and/or parts obsolescence, major modernization of fire alarm system components (panels, pull stations, horns/strobes, detectors, hoses) is typically necessary on a 20-30 year schedule. Utilizing a mid-range 25 year life cycle reflects a 2045 expense date. The current average per unit cost estimate is based on actual costs incurred during the 2020 project, as reported by the association. As this project was completed since our most recent inspection, no photograph was included.

PRN:10/23/2021 Page 40 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Fire Pump/Equipment

Item Number	39			Me	easurement Basis		lp sm
Туре	Common Are	a		Est	imated Useful Life		45 Years
Category	Mechanical/E	Electrical		Bas	sis Cost		79,420.00
Tracking	Logistical			Sal	vage Value		\$ 0.00
Method	Fixed						
	Service	Replace	Rem	Adj		Current	Future
Code Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0039	06/01/2001	06/01/2046	24:05	45:00	1	79,420.00	79,420.00
						79,420.00	79,420.00
Comments							

The 750 gallons per minute diesel fire pump should not require total replacement for 35-50+ years, based on compilation of data from older buildings with both diesel fire pumps and diesel generators. This useful life assumes routine maintenance and the need for periodic rebuilds/rehab projects. This fund is designed to provide monies for as needed repairs to and eventual replacement over a 45 year life cycle. The current replacement cost estimate includes the controller panel, fittings, valves, etc.



Under normal operating conditions, total replacement of the fire sprinkler systems and associated plumbing should not be necessary at any one given time. It is our experience that associations typically fund sprinkler system costs through an annual service contract, and that replacements and upgrades are completed on an incidental, as needed basis through the association's operating budget. As such, no reserves for the fire sprinkler systems were included in this report.

PRN:10/23/2021 Page 41 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Garage Gates/Equipment

Comments

Item Numbe	er	40			Me	easurement Basi	S	lp sm
Туре		Common Are	a		Esti	imated Useful Life		14 Years
Category		Mechanical/E	lectrical		Bas	sis Cost		17,880.00
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
920-002-0040	South	07/01/2021	07/01/2035	13:06	14:00	1	17,880.00	17,880.00
920-001-0040	North	05/01/2016	05/01/2030	8:04	14:00	1	17,880.00	17,880.00
						_	35,760.00	35,760.00

Barring any unforeseen vehicular damage, replacement of the roll up garage gates and associated motors, etc. should be expected on a market observed life cycle in the mid-10 to 20 year range. Since they may not require replacement concurrently, we have included a separate line item for each. At the association's prior request and sole discretion, replacements were forecast on recurring 14 year life cycles.





PRN:10/23/2021 Page 42 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Generator/Equipment

Item Numb	er	41			Me	easurement Basis		kW
Туре		Common Are	а		Est	imated Useful Life		40 Years
Category		Mechanical/E	Electrical		Bas	sis Cost		484.75
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0041		06/01/2001	06/01/2041	19:05	40:00	200	96,950.00	96,950.00
							96,950.00	96,950.00
Comments								

The 200 kW diesel generator has an estimated useful life of 35-40+ years. This fund is designed to provide monies for as needed repairs to and eventual replacement over a 40 year life cycle. The current replacement cost estimate includes the transfer switch, fuel tank, and other associated equipment.





PRN:10/23/2021 Page 43 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Hallways Outside Air Unit

Item Number	46			Me	asurement Basis		tons
Туре	Common Are	a		Est	imated Useful Life		12 Years
Category	Mechanical/E	Electrical		Bas	sis Cost		2,849.70
Tracking	Logistical			Sal	vage Value		\$ 0.00
Method	Fixed						
	Service	Replace	Rem	Adj		Current	Future
Code Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0046	08/01/2016	08/01/2028	6:07	12:00	40	113,988.00	113,988.00
						113,988.00	113,988.00
Comments							

The roof mounted 40 ton package/RTU unit supporting the common area hallway interiors was replaced in 2016. Data gleaned from similar properties reflects a probable life cycle in the 10 to low 10 year range, and a 2028 expense date scheduled accordingly. The current cost estimates includes removal and disposal of the existing unit, typical permitting and consulting fees, and installation of a unit of like size and quality.



PRN:10/23/2021 Page 44 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Trash Chute Doors

Item Nur	mber	101			Me	asurement Basis		lp sm
Туре		Common Are	ea		Esti	mated Useful Life		24 Years
Category	•	Mechanical/	Electrical		Bas	sis Cost		30,160.00
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-01	.01		06/01/2025	3:05	24:00	0	0.00	0.00
Commer	nts							

None of the individual trash chute doors has a current repair/replacement cost of \$10,000+, so their inclusion in the association's estimate of full statutory reserve funding for fiscal year 2022 is not mandated under current Florida Statute 718 requirements. Some associations prefer to fund as needed repair/replacement projects through their annual operating budgets, as a function of routine maintenance. Others do establish and fund reserves for repairs/replacements. At the association's request and sole discretion, no reserves were included for trash chute doors. For the association's consideration, it is our market observation that while some may require replacement sooner than others due to improper use, etc., data gleaned from both within and outside the southwest Florida marketplace reflects a probable life cycle in the low to mid 20 year range for replacement of the inventory of trash chute doors; properties with less units/usage tend towards the higher end of that range. We estimate a current inventory replacement cost of \$30,160 for the 40 doors.



PRN:10/23/2021 Page 45 of 122

Analysis Date - January 1, 2022 Item Parameters - Full Detail

Tr	ash	Ch	utes	:

Item Nur	nber	100			Me	asurement Basis		lp sm
Туре		Common Are	ea .		Esti	mated Useful Life		40 Years
Category		Mechanical/I	Electrical		Bas	sis Cost		148,890.00
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-01	00		06/01/2041	19:05	40:00	0	0.00	0.00
Commer	nts							

Data taken from older properties suggests that major trash chute restoration/replacement should be expected on a 35-40+ year basis, which assumes typical and routine maintenance. Some associations do establish and fund restoration/replacement reserves, while others prefer to fund as needed repairs through their annual operating budgets.

At the association's prior request and sole discretion, no reserves were included for eventual major restoration/replacement of the trash chutes. For the association's consideration, we estimate a current per floor cost of \$3,545, which reflects a total current cost of \$148,890 for the 42 floors of trash chutes.



PRN:10/23/2021 Page 46 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Video Surveillance System

Item Num	ber	133			Me	asurement Basis		cameras
Туре		Common Area	a		Esti	mated Useful Life		11 Years
Category		Mechanical/E	lectrical		Bas	sis Cost		1,344.00
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-013	3	10/01/2019	10/01/2030	8:09	11:00	12	16,128.00	16,128.00
							16,128.00	16,128.00
Comment	S							

Data gleaned from both within and outside the local market area indicates that while minor component repairs/replacements (cameras, monitors, recording equipment, hardware/software, etc.) can be expected as a function of ongoing maintenance, total system modernization and/or replacement can be expected on a life cycle in the 10-12 year range. The current per camera cost estimate is reflective of the entire system.

PRN:10/23/2021 Page 47 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Water Softener System/Equipment

Item Numb	er	137			Me	easurement Basis		lp sm
Туре		Common Are	a		Esti	imated Useful Life		10 Years
Category		Mechanical/E	lectrical		Bas	sis Cost		17,000.00
Tracking		Logistical			Sal	Salvage Value		\$ 0.00
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0137		06/01/2021	01/01/2032	10:00	10:07	1	17,000.00	17,000.00
							17,000.00	17,000.00
Comments								

At the association's request and sole discretion, reserves for modernization/replacement of the common area water softener system/equipment we included over a recurring 10 year life cycle, with the next expense forecast in 2032.

PRN:10/23/2021 Page 48 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Paint Garage Ceilings/Piping

Item Numb	er	54			Me	easurement Basis		sq ft
Туре		Common Are	a		Est	imated Useful Life		20 Years
Category		Painting & Wa	aterproofing		Bas	sis Cost		0.83
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0054		06/01/2001	09/01/2027	5:08	26:03	42,000	34,860.00	34,860.00
							34,860.00	34,860.00
Comments								

While not typically necessary on as frequent a life cycle as exterior painting, data gleaned from better quality properties both within and outside the local market area indicates that third party repainting of the garage ceilings, walls, posts, etc. should be expected in the foreseeable future. Life cycles in the 15-20 year range have been observed, which recognizes that as needed touch ups/repairs will be completed using in house labor, as a function of routine maintenance. At the association's request and sole discretion, repainting of the ceilings/piping was adjusted to reflect a 2027 expense date. A recurring 20 year life cycle was forecast thereafter. The total painted area is a rounded estimate.



Painting/refinishing of the garage floors is reportedly completed using in house labor, and was therefore excluded from this report. This report assumes that as needed interior painting of storage areas, service rooms, etc. will be completed using in house labor as well, typical of the subject's location and quality.

PRN:10/23/2021 Page 49 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Paint Garage Walls/Doors

Item Numb	er	134			Me	asurement Basis		sq ft
Туре		Common Area	a		Esti	mated Useful Life		18 Years
Category		Painting & Wa	aterproofing		Bas	sis Cost		0.54
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0134		08/01/2019	08/01/2037	15:07	18:00	42,000	22,680.00	22,680.00
							22,680.00	22,680.00
Comments								

While not typically necessary on as frequent a life cycle as exterior painting, data gleaned from better quality properties both within and outside the local market area indicates that third party repainting of the garage ceilings, walls, posts, etc. should be expected in the foreseeable future. Life cycles in the 15-20 year range have been observed, which recognizes that as needed touch ups/repairs will be completed using in house labor, as a function of routine maintenance. At the association's request and sole discretion, the remaining useful life for repainting of the ceilings/piping was adjusted to reflect a 2023 expense date (to be completed concurrently with the scheduled exterior painting/waterproofing project). A recurring 20 year life cycle was forecast thereafter. The total painted area is a rounded estimate.



PRN:10/23/2021 Page 50 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Paint Stairways Interiors

Item Numbe	er	71			Me	easurement Basis		flights
Туре		Common Are	a		Esti	imated Useful Life		20 Years
Category		Painting & Wa	aterproofing		Bas	sis Cost		882.25
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0071		06/01/2001	09/01/2023	1:08	22:03	42	37,054.50	37,054.50
							37,054.50	37,054.50
Comments								

Given the secondary cosmetic nature of the common area interior stairways, interior painting is not typically necessary on as frequent a life cycle as exterior painting. Life cycles in the 15-25+ year range have been observed, which recognizes that as needed touch ups/repairs will be completed using in house labor, as a function of routine maintenance. At the association's prior request and sole discretion, the remaining useful life was adjusted to reflect a 2023 expense date, to be completed concurrently with the scheduled exterior painting/waterproofing project. A recurring 20 year life cycle was forecast thereafter.



PRN:10/23/2021 Page 51 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Paint/Waterproof Building Exteriors

Item Numb	er	55			Me	easurement Basis		units
Туре		Common Are	a		Est	imated Useful Life		7 Years
Category		Painting & Wa	aterproofing		Bas	sis Cost		4,697.00
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0055		07/01/2016	07/01/2023	1:06	7:00	72	338,184.00	338,184.00
							338,184.00	338,184.00
Comments								

To insure proper protection of the underlying concrete, stucco, wood and metal surfaces, a maximum 7 year life cycle is the market norm we have observed for exterior painting and waterproofing (in lieu of an association purchased longer year warranty). The association purchased a 7 year warranty with its 2016 exterior painting and waterproofing project, and a 2023 expense date forecast accordingly. The current average per dwelling unit cost estimate includes typical minor concrete/stucco repairs, surface preparation, as needed window and sliding glass door caulking, and repainting/refinishing of all exterior concrete, stucco, wood and metal surfaces (including railings and window/slider frames).









PRN:10/23/2021 Page 52 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Structural/Concrete/Stucco

Item Nur	mber	132			Me	asurement Basis		
Туре		Common Are	ea		Esti	imated Useful Life		0 Year
Category	1	Painting & W	aterproofing		Bas	sis Cost		0.00
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code Desc.		Date	Date	Life	Life	Quantity	Cost	Cost
910-000-01	132		06/01/2001	0:00	0:00	0	0.00	0.00
Commer	nts							

A determination of the condition of the exterior concrete systems is beyond the scope of this report. While it is certain that some measure of concrete restoration will be necessary in any property of the subject's design and construction with exposure to the ocean elements, it is very difficult to quantify budgetary costs and remaining useful lives. It is our market observation that very few associations establish and fund major concrete restoration reserves, given the relative uncertainty of cost and useful life; it is much more common for these upgrades to be funded (at least partially) via special assessment. No reserves for concrete restoration were included in this report. Should the association wish to include reserves for concrete restoration, a budgetary funding goal and useful life cycle would need to be provided.



PRN:10/23/2021 Page 53 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Asphalt Paving (Replacement)

Item Numb	er	56			Me	easurement Basis		sq yds
Туре		Common Are	a		Est	imated Useful Life		20 Years
Category		Pavement			Bas	sis Cost		15.59
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0056	i	06/01/2001	09/01/2027	5:08	26:03	3,760	58,618.40	58,618.40
							58,618.40	58,618.40
Comments	;							

Resurfacing/overlaying of the asphalt paved parking and drives has been observed on life cycles in the mid-10 to 20 year range in better quality properties like the subject. The existing asphalt paving was observed to be deteriorating/cracking, and appears to be in need of near future replacement. At the association's prior request and sole discretion, this expense was forecast in 2027. Based on the observed condition of areas of existing paving, this adjustment will likely result in a poorer appearance and possibly higher replacement costs. The current cost estimate includes as needed milling of the asphalt at its junction with adjacent concrete/pavers, typical minor upgrades to the drainage systems and structural repairs, the installation of a standard overlay, re-striping, and curb stops replacement.



Replacement of concrete paving (curbing, sidewalks, decking, etc.) should not be necessary at any one given time under normal operating conditions. As such, reserving for total replacement is not considered practical or prudent. Associations commonly fund minor upgrades to these paving systems on an as needed, incidental basis as a function of their general operating budgets, given the unpredictability of cost and time frames. Therefore, no reserve was established for the common area concrete paving.

PRN:10/23/2021 Page 54 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Asphalt Paving (Sealcoat/Rejuvenation)

Comments

Item Numb	er	70			Me	asurement Basis		sq yds
Туре		Common Are	ea		Esti	mated Useful Life		3 Years
Category		Pavement			Bas	is Cost		1.97
Tracking		Logistical			Salv	vage Value		\$ 0.00
Method		One Time						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
920-005-0070	1		06/01/2039	17:05	17:05	3,760	7,407.20	7,407.20
920-007-0070)		06/01/2045	23:05	23:05	3,760	7,407.20	7,407.20
920-006-0070	1		06/01/2042	20:05	20:05	3,760	7,407.20	7,407.20
920-004-0070	1		06/01/2036	14:05	14:05	3,760	7,407.20	7,407.20
920-001-0070	1		06/01/2023	1:05	3:00	3,760	7,407.20	7,407.20
920-002-0070	1		06/01/2030	8:05	8:05	3,760	7,407.20	7,407.20
920-003-0070)		06/01/2033	11:05	11:05	3,760	7,407.20	7,407.20
							51,850.40	51,850.40

Some associations complete sealcoating/rejuvenation of their common area asphalt paving on a periodic and regular basis, to insure a high cosmetic appeal and the maximum useful life of their asphalt paving; 3-4 year life cycles are most typically observed. Other associations are of the opinion that this project is strictly cosmetic, and do not. This project was completed in 2020 and scheduled again in 2023. Recurring 3 year life cycles were scheduled after the forecast 2027 repaving and 2047 repaving projects. The current cost estimate includes typical minor pavement repairs and re-striping.



PRN:10/23/2021 Page 55 of 122


Analysis Date - January 1, 2022

Item Parameters - Full Detail

Drives/Parking Pavers

Item Number		57			Me	easurement Basis		sq ft
Туре		Common Area	a		Est	imated Useful Life		25 Years
Category		Pavement			Ba	sis Cost		6.66
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Code De	esc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0057		06/01/2001	09/01/2027	5:08	26:03	8,200	54,612.00	54,612.00
							54,612.00	54,612.00
Comments								

Some associations consider paver parking/drives, walkways, pool and spa decks, etc. to be effectively permanent, and opt to exclude replacement from their annual reserve budgets. Others do establish and fund reserves for replacement, on observed budgetary life cycles of 20-40 years. It is our opinion that reserving for eventual replacement is prudent, if only for cosmetic purposes; we have observed older pavers that appear worn and dated, even with periodic pressure washing and/or sealing. This fund is designed to provide monies for as needed repairs to and eventual replacement of the pavers at the main entry, porte cochere and parking over a 25 year life cycle. At the association's request and sole discretion, the remaining useful life was adjusted to reflect a 2027 expense date. The total area is a rounded estimate.



PRN:10/23/2021 Page 56 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Common Area Plumbing

Item Nur	mber	131			Me	easurement Basis		
Туре		Common Are	ea		Esti	imated Useful Life		0 Year
Category	,	Plumbing			Bas	sis Cost		0.00
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code Desc.		Date	Date	Life	Life	Quantity	Cost	Cost
910-000-01	131		06/01/2001	0:00	0:00	0	0.00	0.00
Commer	nts							

Under normal conditions, total replacement of the common area plumbing lines/piping should not be necessary at any one given time. Therefore, it is our opinion that reserving for total replacement is not prudent or practical, which is supported by our review of reserve budgets at similar properties. While some associations do establish and fund contingency reserves for unpredictable and expected common area plumbing repairs, other associations prefer to fund unforeseen common area plumbing repairs (at least partially) via special assessment. At such time as the association can provide a budgetary funding goal and time frame in which to reach that goal, if a common area plumbing reserve is desired, this report can be amended accordingly.

PRN:10/23/2021 Page 57 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Deck Furniture

Item Num	ber	59			Me	easurement Basis		pieces
Туре		Common Area	a		Est	imated Useful Life		12 Years
Category		Pool & Spa			Ba	sis Cost		415.40
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-005	9	10/01/2021	10/01/2033	11:09	12:00	65	27,001.00	27,001.00
							27,001.00	27,001.00
Comment	:s							

While miscellaneous replacements will be necessary on an ongoing basis, and recognizing that periodic refinishing and re-slinging will be necessary as a function of routine maintenance, the market suggests a useful life in the 10 to mid-10 year range for replacement of the deck furniture inventory. The current per piece cost estimate is an average figure, and includes chaise lounges, occasional tables, bar stools, chairs, trash receptacles, etc.).



PRN:10/23/2021 Page 58 of 122

Analysis Date - January 1, 2022 Item Parameters - Full Detail

Decking								
Item Num	nber	58			Me	asurement Basis		sq ft
Туре		Common Are	a		Esti	mated Useful Life		25 Years
Category		Pool & Spa			Bas	is Cost		6.66
Tracking		Logistical			Salv	vage Value		\$ 0.00
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-005	58	06/01/2001	06/01/2027	5:05	26:00	5,830	38,827.80	38,827.80
							38,827.80	38,827.80
Commen	ts							

Some associations consider paver parking/drives, walkways, pool and spa decks, etc. to be effectively permanent, and opt to exclude replacement from their annual reserve budgets. Others do establish and fund reserves for replacement, on observed budgetary life cycles of 20-40 years. It is our opinion that reserving for eventual replacement is prudent, if only for cosmetic purposes; we have observed older pavers that appear worn and dated, even with periodic pressure washing and/or sealing. At the association's request and sole discretion, this expense was forecast in 2027. The total area is a rounded estimate.



PRN:10/23/2021 Page 59 of 122


Analysis Date - January 1, 2022

Item Parameters - Full Detail

Fencing/Gates

Item Number		103			Me	easurement Basis		In ft
Туре		Common Area	Э		Est	imated Useful Life		24 Years
Category		Pool & Spa			Ba	sis Cost		59.43
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Code Des	ic.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0103		06/01/2001	06/01/2027	5:05	26:00	348	20,681.64	20,681.64
							20,681.64	20,681.64
Comments								

Barring any unforeseen storm damages, etc., the decorative metal fencing and gates and the pool perimeter should have a life cycle in the low to mid 20 year range. At the association's prior request and sole discretion, this expense was forecast in 2027, which is reflective of a +/- 26 year life cycle. This is longer than we have typically observed, and may result in deteriorated/unsightly fencing. The current per linear foot unit cost includes removal and disposal of the existing fencing and gates and installation of like height/quality fencing and gates.



PRN:10/23/2021 Page 60 of 122

Analysis Date - January 1, 2022 Item Parameters - Full Detail

Heaters								
Item Numb	oer	60			Measurement Basis			
Туре		Common Are	a		Esti	mated Useful Life		15 Years
Category		Pool & Spa			Bas	is Cost		7,826.00
Tracking		Logistical		Salvage Value				\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
920-004-0060)	06/01/2021	06/01/2036	14:05	15:00	1	7,826.00	7,826.00
920-002-0060)	06/01/2013	06/01/2028	6:05	15:00	1	7,826.00	7,826.00
920-003-0060)	06/01/2021	06/01/2036	14:05	15:00	1	7,826.00	7,826.00
920-001-0060)	06/01/2019	06/01/2034	12:05	15:00	1	7,826.00	7,826.00
							31,304.00	31,304.00
Comments	5							

The geothermal pool and spa heaters installed in 2004 should have a life cycle in the mid-10 to low 20 year range, based on our discussions with pool heater contractors and associations that have installed these systems. At the association's request, replacements were scheduled on recurring 15 year life cycles.



Under normal conditions, total pool and spa equipment inventory (pumps, filters, chlorination systems, etc.) replacement should not be necessary at any one given time. As such, it is not uncommon for associations like the subject to fund as needed repairs/replacements through their annual operating budgets, as a function of routine maintenance. No reserves for this equipment were included in this report.

PRN:10/23/2021 Page 61 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Interiors Resurfacing

Item Number	61			Me	easurement Basis		sq ft
Туре	Common Ar	ea		Esti	imated Useful Life		10 Years
Category	Pool & Spa			Bas	sis Cost		18.10
Tracking	Logistical			Sal	vage Value		\$ 0.00
Method	Adjusted						
	Service	Replace	Rem	Adj		Current	Future
Code Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0061	08/23/2012	08/01/2024	2:07	12:00	1,350	24,435.00	24,435.00
						24,435.00	24,435.00
Comments							

Assuming proper installation, chemical balancing, and routine maintenance, the typical concrete pool and spa with marcite or aggregate interiors should require resurfacing on a +/- 10 year life cycle. Based on the summer 2012 completion date of this project and the association's completion of a +/- \$7,500 expense in 2015, the remaining useful life for this project was adjusted to reflect a summer 2024 expense date. A recurring 10 year life cycle was scheduled thereafter. The current cost estimate includes typical minor tank/structural repairs, tile upgrades, and installation of new aggregate surface materials (i.e. "diamond brite", "pebble crete", etc.).





PRN:10/23/2021 Page 62 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Summer Kitchen

Comments

Item Nur	mber	123			Me	asurement Basis		lp sm
Туре		Common Are	a		Esti	mated Useful Life		14 Years
Category	,	Pool & Spa			Bas	sis Cost		9,550.00
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-01	.23	01/01/2015	01/01/2029	7:00	14:00	1	9,550.00	9,550.00
							9,550.00	9,550.00

This fund is designed to provide monies for eventual major restoration of the poolside summer kitchen (counters, etc.) over a 14 year life cycle. The current cost estimate is based on reported costs incurred during the 2015 project, and is not reflective of total replacement. Under normal conditions, we do not anticipate total replacement in the foreseeable future.



The association expects to complete as needed grills repair/replacements as a function of ongoing maintenance, funded through their annual operating budgets.

PRN:10/23/2021 Page 63 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Decktop Railings

		407						1 6
Item Number	r	107			IVIE	asurement Basis		In ft
Type		Common Area	a		Esti	mated Useful Life		30 Years
Category		Railings/Scree	en Enclosures		Bas	sis Cost		73.53
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0107		06/01/2001	06/01/2031	9:05	30:00	520	38,235.60	38,235.60
							38,235.60	38,235.60
Comments								

At some point, the association should expect to incur costs for replacement of the exterior railings and screen enclosures supporting the individual unit lanais, parking garage interiors and garage rooftop lawns/decks. We have observed life cycles of less than 20 years, while some properties of similar design and oceanfront/oceanside location of 30+ years in age have yet to complete replacement. This reserve is designed to provide monies for as needed repairs to and eventual replacement of the +/- 880 linear feet of railings at the garage rooftop lawns/decks over a 30 year life cycle. The current cost estimate includes removal and disposal of the existing railings and typical minor concrete repairs.



PRN:10/23/2021 Page 64 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Garage Screen Enclosures

Item Number	108			Me	asurement Basis		sq ft
Туре	Common Are	ea		Esti	mated Useful Life		25 Years
Category	Railings/Scre	en Enclosures		Bas	sis Cost		11.13
Tracking	Logistical			Sal	vage Value		\$ 0.00
Method	Fixed						
	Service	Replace	Rem	Adj		Current	Future
Code Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0108	06/01/2014	06/01/2039	17:05	25:00	2,560	28,492.80	28,492.80
						28,492.80	28,492.80
Comments							

At some point, the association should expect to incur costs for replacement of the screen enclosures supporting the individual unit lanais and parking garage interiors. We have observed life cycles of less than 20 years, while some properties of similar design and oceanfront/oceanside location of 30+ years in age have yet to complete replacement. This project was completed in 2014; this fund is designed to provide monies for as needed repairs to and eventual replacement over a 25 year life cycle.



This report assumes that as needed repairs/replacement of screening will be funded through the association's annual operating budget, as a function of routine maintenance, as typically observed in the market area.

PRN:10/23/2021 Page 65 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Units Railings/Screen Enclosures/Doors

Category Railings/Screen Enclosures Basis Cost 242 Tracking Logistical Salvage Value Method Fixed Adj Current Code Desc. Date Date Life Life Quantity Cost 910-000-0106 06/01/2014 06/01/2039 17:05 25:00 1 242,307.00 2		<u> </u>							
Category Railings/Screen Enclosures Basis Cost 242 Tracking Logistical Salvage Value Method Fixed Adj Current Code Desc. Date Date Life Life Quantity Cost 910-000-0106 06/01/2014 06/01/2039 17:05 25:00 1 242,307.00 2	Item Nur	mber	106			Me	asurement Basis		lp sm
Tracking Logistical Salvage Value Method Fixed Service Replace Rem Adj Current Code Desc. Date Date Date Life Life Quantity Cost 910-000-0106 06/01/2014 06/01/2039 17:05 25:00 1 242,307.00 2 2	Туре		Common Are	a		Esti	mated Useful Life		25 Years
Method Fixed Service Replace Rem Adj Current Code Desc. Date Date Life Life Quantity Cost 910-000-0106 06/01/2014 06/01/2039 17:05 25:00 1 242,307.00 2	Category	,	Railings/Scree	en Enclosures		Bas	sis Cost		242,307.00
Service Replace Rem Adj Current Code Desc. Date Date Life Life Quantity Cost 910-000-0106 06/01/2014 06/01/2039 17:05 25:00 1 242,307.00 2	Tracking		Logistical			Sal	vage Value		\$ 0.00
Code Desc. Date Date Life Life Quantity Cost 910-000-0106 06/01/2014 06/01/2039 17:05 25:00 1 242,307.00 2	Method		Fixed						
910-000-0106 06/01/2014 06/01/2039 17:05 25:00 1 242,307.00 2			Service	Replace	Rem	Adj		Current	Future
	Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
242,307.00 2	910-000-01	106	06/01/2014	06/01/2039	17:05	25:00	1	242,307.00	242,307.00
							_	242,307.00	242,307.00

Comments

At some point, the association should expect to incur costs for replacement of the exterior railings and screen enclosures/sliding screen doors supporting the individual unit lanais, parking garage interiors and garage rooftop lawns/decks. We have observed life cycles of less than 20 years, while some properties of similar design and oceanfront/oceanside location of 30+ years in age have yet to complete replacement. Replacement was completed in 2014; this fund is designed to provide monies for as needed repairs to and eventual replacement over a 25 year life cycle. The current cost estimate for the screen enclosures and railings at the unit lanais is a rounded estimate based on the total of +/- 2,285 linear feet of screen enclosures at a \$82.55/linear foot unit cost plus the total of +/- 880 linear feet of railings at a \$61.00/linear foot unit cost. This cost includes removal and disposal of the existing screen enclosures/railings and typical minor concrete repairs.



PRN:10/23/2021 Page 66 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Units Screening Replacement

Item Numbe	er	135			Me	asurement Basis		lanais
Туре		Common Area	a		Esti	mated Useful Life		12 Yr 6 Mn
Category		Railings/Scree	en Enclosures		Bas	sis Cost		595.00
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0135		06/01/2014	12/01/2026	4:11	12:06	120	71,400.00	71,400.00
							71,400.00	71,400.00
Comments								

The association is reportedly responsible for replacement of the fiberglass screening in the unit balcony screen enclosures, most recently completed in 2014. This fund is designed to provide monies for recurring screening replacement on a 12.5 year life cycle. This life cycle is consistent with the actual operating history and the estimated 25 year life cycle for screen enclosures replacement. The current per lanai cost estimate is n average figure.



PRN:10/23/2021 Page 67 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Mechanical Building Roofing

Item Nur	mber	64			Me	asurement Basis		sqs
Туре		Common Are	a		Esti	mated Useful Life		26 Years
Category	,	Roofing			Bas	sis Cost		1,528.00
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-00	064	06/01/2001	06/01/2027	5:05	26:00	10.65	16,273.20	16,273.20
							16,273.20	16,273.20

Comments

The pitched tile roof covers on the mechanical building, pool pavilion and porte cochere have a market indicated life cycle of 25-30 years, assuming proper design, installation and maintenance; the most typical life falls in the mid-20 year range, assuming proper design, installation and routine maintenance. As no professional roofing studies were provided that would suggest that physical conditions exist at these roofs that would otherwise limit their remaining useful lives, reserves were included to provide monies for as needed repairs to and eventual replacement over 26 year life cycles. The current cost estimates include consulting/permitting removal and disposal of the existing roofing, typical minor repairs to the underlying roof structures, flashing, as needed repair/replacement of fascia, soffits, and/or gutters and downspouts, and installation of like roofing. One square = 100 square feet.



PRN:10/23/2021 Page 68 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Pool Pavilion Roofing

mmon Area						sqs
iiiiiioii Ai ca			Est	imated Useful Life		26 Years
ofing			Ва	sis Cost		1,528.00
racking Logistical Nethod Fixed			Sal	vage Value		\$ 0.00
ed						
Service	Replace	Rem	Adj		Current	Future
Date	Date	Life	Life	Quantity	Cost	Cost
06/01/2001	06/01/2027	5:05	26:00	7	10,696.00	10,696.00
					10,696.00	10,696.00
	sed Service	gistical red Service Replace Date Date	gistical red Service Replace Rem Date Date Life	gistical Sal red Service Replace Rem Adj Date Date Life Life	Salvage Value Service Replace Rem Adj Date Date Life Life Quantity	Salvage Value Service Replace Rem Adj Current Date Date Life Life Quantity Cost

The pitched tile roof covers on the mechanical building, pool pavilion and porte cochere have a market indicated life cycle of 25-30 years, assuming proper design, installation and maintenance; the most typical life falls in the mid-20 year range, assuming proper design, installation and routine maintenance. As no professional roofing studies were provided that would suggest that physical conditions exist at these roofs that would otherwise limit their remaining useful lives, reserves were included to provide monies for as needed repairs to and eventual replacement over 26 year life cycles. The current cost estimates include consulting/permitting removal and disposal of the existing roofing, typical minor repairs to the underlying roof structures, flashing, as needed repair/replacement of fascia, soffits, and/or gutters and downspouts, and installation of like roofing. One square = 100 square feet.



PRN:10/23/2021 Page 69 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Porte Cochere Roofing

Item Numbe	er	66			Me	easurement Basis		sqs
Туре		Common Area	a		Est	imated Useful Life		26 Years
Category		Roofing			Ва	sis Cost		1,528.00
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0066		06/01/2001	06/01/2027	5:05	26:00	20.3	31,018.40	31,018.40
							31,018.40	31,018.40
Comments								

The pitched tile roof covers on the mechanical building, pool pavilion and porte cochere have a market indicated life cycle of 25-30 years, assuming proper design, installation and maintenance; the most typical life falls in the mid-20 year range, assuming proper design, installation and routine maintenance. As no professional roofing studies were provided that would suggest that physical conditions exist at these roofs that would otherwise limit their remaining useful lives, reserves were included to provide monies for as needed repairs to and eventual replacement over 26 year life cycles. The current cost estimates include consulting/permitting removal and disposal of the existing roofing, typical minor repairs to the underlying roof structures, flashing, as needed repair/replacement of fascia, soffits, and/or gutters and downspouts, and installation of like roofing. One square = 100 square feet.



PRN:10/23/2021 Page 70 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Tower Roofing (Flat)

	· · · · · · · · · · · · · · · · · · ·							
Item Nur	mber	62			Me	asurement Basis	5	sqs
Туре		Common Are	a		Esti	mated Useful Life		20 Years
Category	,	Roofing			Bas	sis Cost		3,281.50
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Adjusted						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-00)62	06/01/2001	10/01/2024	2:09	23:04	88	288,772.00	288,772.00
						_	288,772.00	288,772.00

Comments

The flat/membrane roofing on the tower building should require replacement on an 20 year schedule under normal operating conditions; the tower flat roofing was observed to be in average to good overall condition, and appears to have been well maintained. No significant problems were reported by the property manager. As such, the indicated replacement date is at or near 2021. A roof assessment completed in spring 2019 by Crowther Roofing indicates that the existing roofing is in good condition, and that replacement does not appear likely for the next 3+ years. As such, the remaining useful life was adjusted to reflect a 2024 expense date. The current replacement cost estimate includes consulting/permitting, tear off and disposal of the existing roof covers, typical minor repairs to the underlying roof structures, flashing, etc. and installation of similar roofing. One square = 100 square feet.



PRN:10/23/2021 Page 71 of 122


Analysis Date - January 1, 2022

Item Parameters - Full Detail

Tower Roofing (Metal Shingle)

Item Number Type Category		63 Common Area				Measurement Basis Estimated Useful Life		sqs
								35 Years
		Roofing			Ва	Basis Cost		4,566.70
Tracking		Logistical			Salvage Value			\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0063	3	06/01/2001	06/01/2036	14:05	35:00	56.5	258,018.55	258,018.55
							258,018.55	258,018.55
Comment	S							

The tower building features coated metal shingle roof covers. This roofing product is relatively new, compared with pitched tile, shingle, etc. roofing; as such, there is very little actual market extracted data by which a useful life can be estimated. Discussions with roofing consultants and associations that have installed this type of roofing reflects an expected life cycle of 30-40+ years. This useful life assumes proper design, installation, and routine maintenance. This fund is designed to provide monies for as needed repairs to (it appears repairs/cleaning should be completed in the near future, to insure a high cosmetic appeal) and eventual replacement of this roofing over a 35 year life cycle. The current unit cost estimate includes consulting/permitting, removal and disposal of the existing roofing, typical minor repairs to the underlying roof structures, flashing, etc. and installation of like roofing. One square = 100 square feet.



PRN:10/23/2021 Page 72 of 122

Analysis Date - January 1, 2022 Item Parameters - Full Detail

Landscap	oing										
Item Nu	mber	130			Me	Measurement Basis					
Туре		Common Are	ea		Esti		0 Year				
Category	•	Site Improve	ments		Bas	Basis Cost					
Tracking		Logistical			Sal	vage Value		\$ 0.00			
Method		Fixed									
		Service	Replace	Rem	Adj		Current	Future			
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost			
910-000-01	910-000-0130		06/01/2001	0:00	0:00	0	0.00	0.00			
Commer	nts										

In our experience, some associations do establish and fund landscaping reserves, typically on a contingency basis for unforeseen storm damage, blight, etc. Because landscaping is largely cosmetic, costs and useful lives can vary, often widely, from property to property. Given this unpredictability, we include landscaping reserves only when provided current cost and useful life/remaining useful live parameters by an association, and then include at that association's sole discretion. At such time as the association can provide a budgetary funding goal and time frame in which to reach that goal for their common area landscaping, this report can be amended accordingly.



As needed upgrades to irrigation systems is typically funded through an association's annual operating budget, as a function of routine maintenance; we have not encountered an association that has established and funded a reserve for total replacement in the absence of an engineering report demonstrating the need and/or economic feasibility of total irrigation system replacement..

PRN:10/23/2021 Page 73 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

Signage Allowance

Item Number	109			Me	easurement Basis		lp sm
Туре	Common Are	a		Esti		20 Years	
Category	Site Improve	ments		Bas	sis Cost		10,000.00
Tracking	Logistical			Sal	vage Value		\$ 0.00
Method	Adjusted						
	Service	Replace	Rem	Adj		Current	Future
Code Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0109	06/01/2001	01/01/2027	5:00	25:07	1	10,000.00	10,000.00
						10,000.00	10,000.00
Comments							

Under normal conditions, total replacement of the marquee signage structures at the property entry should not be necessary at any one given time. Typically, this type of signage projects involves cosmetic restoration (new tile facades/exteriors, lettering, etc.) rather than total replacement. This fund is designed to provide monies for cosmetic restoration of the two marquee signs; at the association's request and sole discretion, a 2027 expense date was forecast.



PRN:10/23/2021 Page 74 of 122

Analysis Date - January 1, 2022 Item Parameters - Full Detail

VITO.	ıα	hting
JILE	ᇆ	ııtıııe

Item Nur	nber	68			Me	easurement Basis		lp sm		
Туре		Common Are	a		Est	Estimated Useful Life				
Category		Site Improver	nents		Bas	sis Cost		76,685.00		
Tracking		Logistical			Sal	vage Value		\$ 0.00		
Method		Fixed								
		Service	Replace	Rem	Adj		Current	Future		
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost		
910-000-00	68	06/01/2001	06/01/2025	3:05	24:00	1	76,685.00	76,685.00		
							76,685.00	76,685.00		
Commer	nts									

While minor replacements of site lighting (street lights/posts, bollards, landscape lights, etc.) will be necessary from time to time as a function of routine maintenance, better quality properties like the subject typically have completed total inventory replacement after a life cycle in the low to mid 20 year range. This fund is designed to provide monies for as needed replacements over a 24 year life cycle. The current cost estimate is based on cost estimating indexes and our experience with exterior lighting systems in properties of similar quality.



PRN:10/23/2021 Page 75 of 122

Analysis Date - January 1, 2022 Item Parameters - Full Detail

S

Item Number		69			Me	asurement Basis		sq ft
Туре		Common Area	a		Esti	mated Useful Life		14 Years
Category		Site Improver	nents		Bas	sis Cost		29.32
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code D	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0069		10/01/2013	10/01/2027	5:09	14:00	1,800	52,776.00	52,776.00
							52,776.00	52,776.00
Comments								

This category is designed to provide monies for major restoration/replacement of the two wood trellises at the parking structures installed in 2013; assuming proper and routine maintenance, major restorations have been observed on life cycles in the low to mid 10 year range.



PRN:10/23/2021 Page 76 of 122

Analysis Date - January 1, 2022

Item Parameters - Full Detail

West/Nature Preserve Fencing

place.

Item Numbe	er	124			Me	easurement Basis		lp sm
Туре		Common Are	a		Est		24 Years	
Category		Site Improver	ments		Bas	sis Cost		11,855.00
Tracking		Logistical			Sal	vage Value		\$ 0.00
Method		Fixed						
		Service	Replace	Rem	Adj		Current	Future
Code	Desc.	Date	Date	Life	Life	Quantity	Cost	Cost
910-000-0124		01/01/2015	01/01/2039	17:00	24:00	1	11,855.00	11,855.00
							11,855.00	11,855.00
Comments								

Data gleaned from both within and outside the local market area indicates that under normal conditions, replacement of typical coated chain link fencing/gates should be expected on a life cycle in the low to mid-20 year range. This fund is designed to provide monies for as needed repairs to and eventual replacement of the west/nature preserve fencing installed in 2015 over a 24 year life cycle. The current cost estimate is based on actual contract pricing, as provided by the previous property manager. We

reserve the right to modify this report upon confirmation of the factual linear feet in

PRN:10/23/2021 Page 77 of 122

Category	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031
Common Area Interiors										
Billiards Room Furnishings/Finishes				16,352						
Fitness Room Strength Stations/Equip.				29,316						
Guest Suites Furnishings/Finishes		37,900								
Hallways Carpeting		166,467								
Hallways Furnishings/Finishes								233,800		
Lobby/Galleries Furnishings										94,424
Lobby/Galleries Wall/Door Finishes										26,068
Social Room Bar/Kitchen		64,999								
Social Room Carpeting		9,779								
Social Room Furnishings/Finishes						59,946				
-	0	279,145	0	45,668	0	59,946	0	233,800	0	120,492
Engineering Study										
Engineering Study	20,000							20,000		
_	20,000	0	0	0	0	0	0	20,000	0	0
Mechanical/Electrical										
Exhaust/Pressurization Fans										50,380
Garage Gate/Equipment									17,880	
Hallways Outside Air Unit							113,988			
Video Surveillance System									16,128	
-	0	0	0	0	0	0	113,988	0	34,008	50,380
Painting & Waterproofing										
Paint Garage Ceilings/Piping						34,860				
Paint Stairways Interiors		37,054								
Paint/Waterproof Building Exteriors		338,184							338,184	
-	0	375,238	0	0	0	34,860	0	0	338,184	0

Category	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031
Pavement										
Asphalt Paving (Replacement)						58,618				
Asphalt Paving (Sealcoat/Rejuvenation)		7,407							7,407	
Drives/Parking Pavers						54,612				
	0	7,407	0	0	0	113,230	0	0	7,407	0
Pool & Spa										
Decking						38,827				
Fencing/Gates						20,681				
Heaters							7,826			
Interiors Resurfacing			24,435							
Summer Kitchen								9,550		
	0	0	24,435	0	0	59,509	7,826	9,550	0	0
Railings/Screen Enclosures										
Decktop Railings										38,235
Units Screening Replacement					71,400					
	0	0	0	0	71,400	0	0	0	0	38,235
Roofing										
Mechanical Building Roofing						16,273				
Pool Pavilion Roofing						10,696				
Porte Cochere Roofing						31,018				
Tower Roofing (Flat)		<u></u>	288,772							
	0	0	288,772	0	0	57,987	0	0	0	0
Site Improvements										
Signage Allowance						10,000				
Site Lighting				76,685						
Trellises						52,776				
_	0	0	0	76,685	0	62,776	0	0	0	0
	20,000	661,791	313,207	122,353	71,400	388,309	121,814	263,350	379,599	209,107
=										

Category	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041
Common Area Interiors										
Admin. Offices Furnishings/Finishes				11,480						
Elevator Cab Interiors										41,500
Fitness Room Flooring		8,643								
Fitness Room Strength Stations/Equip.									29,316	
Guest Suites Furnishings/Finishes		37,900								
Guest Suites Restrooms								17,205		
Hallways Carpeting						166,467				
Lobby/Galleries Restrooms								46,282		
Social Room Carpeting		9,779								
Social Room Furnishings/Finishes										59,946
-	0	56,322	0	11,480	0	166,467	0	63,488	29,316	101,446
Decks & Planter Boxes										
Lawns/Landscaping Waterproofing		840,750								
Pavers/Waterproofing		345,290								
	0	1,186,040	0	0	0	0	0	0	0	0
Engineering Study										
Engineering Study					20,000					
_	0	0	0	0	20,000	0	0	0	0	0
Mechanical/Electrical										
Domestic Water Pumps/Equipment								48,566		
Garage Gates/Equipment				17,880						
Generator/Equipment										96,950
Hallways Outside Air Unit									113,988	
Video Surveillance System										16,128
Water Softener System/Equipment	17,000									
_	17,000	0	0	17,880	0	0	0	48,566	113,988	113,078

Category	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041
Painting & Waterproofing										
Paint Garage Walls/Doors						22,680				
Paint/Waterproof Building Exteriors						338,184				
_	0	0	0	0	0	360,864	0	0	0	0
Pavement										
Asphalt Paving (Sealcoat/Rejuvenation)		7,407			7,407			7,407		
_	0	7,407	0	0	7,407	0	0	7,407	0	0
Pool & Spa										
Deck Furniture		27,001								
Heater			7,826		15,652					
Interiors Resurfacing			24,435							
_	0	27,001	32,261	0	15,652	0	0	0	0	0
Railings/Screen Enclosures										
Garage Screen Enclosures								28,492		
Units Railings/Screen Enclosures/Doors								242,307		
Units Screening Replacement								71,400		
	0	0	0	0	0	0	0	342,199	0	0
Roofing										
Tower Roofing (Metal Shingle)					258,018					
_	0	0	0	0	258,018	0	0	0	0	0
Site Improvements										
Trellises										52,776
West/Nature Preserve Fencing								11,855		
_	0	0	0	0	0	0	0	11,855	0	52,776
-	17,000	1,276,770	32,261	29,360	301,077	527,331	0	473,516	143,304	267,300

Category	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051
Common Area Interiors										
Billiards Room Furnishings/Finishes				16,352						
Fitness Room Flooring							8,643			
Guest Suites Furnishings/Finishes		37,900								
Hallways Carpeting										166,467
Hallways Furnishings/Finishes		233,800								
Lobby/Galleries Furnishings					94,424					
Lobby/Galleries Wall/Door Finishes					26,068					
Social Room Bar/Kitchen		64,999								
Social Room Carpeting		9,779								
-	0	346,478	0	16,352	120,492	0	8,643	0	0	166,467
Decks & Planter Boxes										
Planter Boxes Waterproofing					202,160					
-	0	0	0	0	202,160	0	0	0	0	0
Engineering Study										
Engineering Study		20,000							20,000	
-	0	20,000	0	0	0	0	0	0	20,000	0
Mechanical/Electrical										
Elevator Mechanical Modernization										584,810
Fire Alarm System Modernization				286,140						
Fire Pump/Equipment					79,420					
Garage Gates/Equipment			17,880					17,880		
Water Softener System/Equipment	17,000									
-	17,000	0	17,880	286,140	79,420	0	0	17,880	0	584,810
Painting & Waterproofing										
Paint Garage Ceilings/Piping						34,860				
Paint Stairways Interiors		37,054								
Paint/Waterproof Building Exteriors			338,184							338,184
-	0	37,054	338,184	0	0	34,860	0	0	0	338,184

Category	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051
Pavement										
Asphalt Paving (Replacement)						58,618				
Asphalt Paving (Sealcoat/Rejuvenation)	7,407			7,407						
	7,407	0	0	7,407	0	58,618	0	0	0	0
Pool & Spa										
Deck Furniture				27,001						
Fencing/Gates										20,681
Heaters		7,826						7,826		15,652
Interiors Resurfacing			24,435							
Summer Kitchen		9,550								
_	0	17,376	24,435	27,001	0	0	0	7,826	0	36,333
Railings/Screen Enclosures										
Units Screening Replacement										71,400
	0	0	0	0	0	0	0	0	0	71,400
Roofing										
Tower Roofing (Flat)			288,772							
	0	0	288,772	0	0	0	0	0	0	0
Site Improvements										
Signage Allowance						10,000				
Site Lighting								76,685		
-	0	0	0	0	0	10,000	0	76,685	0	0
_	24,407	420,908	669,271	336,900	402,072	103,478	8,643	102,391	20,000	1,197,195
-										

Analysis Date - January 1, 2022 Cash Flow - Monthly

Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
\$ 700,000.00	\$ 22,450.00	\$ 385.25	\$ 0.00	\$ 722,835.25
722,835.25	22,450.00	397.62	0.00	745,682.87
745,682.87	22,450.00	409.99	0.00	768,542.86
768,542.86	22,450.00	422.37	0.00	791,415.23
791,415.23	22,450.00	434.76	0.00	814,299.99
814,299.99	22,450.00	441.74	20,000.00	817,191.73
817,191.73	22,450.00	448.73	0.00	840,090.46
840,090.46	22,450.00	461.13	0.00	863,001.59
863,001.59	22,450.00	473.54	0.00	885,925.13
885,925.13	22,450.00	485.96	0.00	908,861.09
908,861.09	22,450.00	498.38	0.00	931,809.47
931,809.47	22,450.00	510.81	0.00	954,770.28
700,000	269,400	5,370	20,000	954,770
Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
\$ 954,770.28	\$ 22,450.00	\$ 523.25	\$ 0.00	\$ 977,743.53
977,743.53	22,450.00	535.69	0.00	1,000,729.22
1,000,729.22	22,450.00	548.14	0.00	1,023,727.36
1,023,727.36	22,450.00	560.60	0.00	1,046,737.96
1,046,737.96	22,450.00	573.06	0.00	1,069,761.02
1,069,761.02	22,450.00	583.53	7,407.20	1,085,387.35
1.085.387.35	22.450.00	502.41	338,184.00	770,155.76
_,,	,			
770,155.76	22,450.00	423.25	0.00	793,029.01
• •	•	423.25 350.00	0.00 316,200.02	793,029.01 499,628.99
770,155.76	22,450.00			•
770,155.76 793,029.01	22,450.00 22,450.00	350.00	316,200.02	499,628.99
770,155.76 793,029.01 499,628.99	22,450.00 22,450.00 22,450.00	350.00 276.71	316,200.02 0.00	499,628.99 522,355.70
	\$ 700,000.00	\$ 700,000.00 \$ 22,450.00 \$ 722,835.25 \$ 22,450.00 \$ 745,682.87 \$ 22,450.00 \$ 768,542.86 \$ 22,450.00 \$ 814,299.99 \$ 22,450.00 \$ 817,191.73 \$ 22,450.00 \$ 863,001.59 \$ 22,450.00 \$ 885,925.13 \$ 22,450.00 \$ 908,861.09 \$ 931,809.47 \$ 22,450.00	\$ 700,000.00 \$ 22,450.00 \$ 385.25 722,835.25 22,450.00 397.62 745,682.87 22,450.00 409.99 768,542.86 22,450.00 434.76 814,299.99 22,450.00 441.74 817,191.73 22,450.00 448.73 840,090.46 22,450.00 461.13 863,001.59 22,450.00 473.54 885,925.13 22,450.00 485.96 908,861.09 22,450.00 498.38 931,809.47 22,450.00 510.81 700,000 269,400 5,370 Begining Balance Contribution Interest Earned \$ 954,770.28 \$ 22,450.00 \$ 523.25 977,743.53 22,450.00 535.69 1,000,729.22 22,450.00 548.14 1,023,727.36 22,450.00 573.06 1,046,737.96 22,450.00 573.06 1,069,761.02 22,450.00 583.53	\$700,000.00 \$22,450.00 \$385.25 \$0.00 722,835.25 22,450.00 397.62 0.00 745,682.87 22,450.00 409.99 0.00 768,542.86 22,450.00 422.37 0.00 814,299.99 22,450.00 441.74 20,000.00 817,191.73 22,450.00 448.73 0.00 840,090.46 22,450.00 461.13 0.00 863,001.59 22,450.00 473.54 0.00 885,925.13 22,450.00 485.96 0.00 908,861.09 22,450.00 498.38 0.00 931,809.47 22,450.00 510.81 0.00 \$\$931,809.47 22,450.00 \$523.25 \$0.00 \$\$954,770.28 \$22,450.00 \$535.69 0.00 977,743.53 22,450.00 \$583.53 7,407.20

PRN:10/23/2021 Page 84 of 122

Analysis Date - January 1, 2022 Cash Flow - Monthly

2024	Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
January	\$ 567,846.06	\$ 22,450.00	\$ 313.66	\$ 0.00	\$ 590,609.72
February	590,609.72	22,450.00	325.99	0.00	613,385.71
March	613,385.71	22,450.00	338.33	0.00	636,174.04
April	636,174.04	22,450.00	350.67	0.00	658,974.71
May	658,974.71	22,450.00	363.02	0.00	681,787.73
June	681,787.73	22,450.00	375.38	0.00	704,613.11
July	704,613.11	22,450.00	387.75	0.00	727,450.86
August	727,450.86	22,450.00	393.50	24,435.00	725,859.36
September	725,859.36	22,450.00	399.25	0.00	748,708.61
October	748,708.61	22,450.00	333.42	288,772.00	482,720.03
November	482,720.03	22,450.00	267.55	0.00	505,437.58
December	505,437.58	22,450.00	279.86	0.00	528,167.44
	567,846	269,400	4,128	313,207	528,167
2025	Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
January	\$ 528,167.44	\$ 22,450.00	\$ 279.80	\$ 45,668.00	\$ 505,229.24
February	505,229.24	22,450.00	279.75	0.00	527,958.99
March	527,958.99	22,450.00	292.06	0.00	550,701.05
April	550,701.05	22,450.00	304.38	0.00	573,455.43
May	573,455.43	22,450.00	316.70	0.00	596,222.13
June	596,222.13	22,450.00	308.27	76,685.00	542,295.40
July	542,295.40	22,450.00	299.82	0.00	565,045.22
August	565,045.22	22,450.00	312.15	0.00	587,807.37
September	587,807.37	22,450.00	324.48	0.00	610,581.85
October	610,581.85	22,450.00	336.81	0.00	633,368.66
November	633,368.66	22,450.00	349.15	0.00	656,167.81
December	656,167.81	22,450.00	361.50	0.00	678,979.31
	528,167	269,400	3,764	122,353	678,979
			3,704		0,0,5,5

PRN:10/23/2021 Page 85 of 122

Analysis Date - January 1, 2022 Cash Flow - Monthly

Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
\$ 678,979.31	\$ 22,450.00	\$ 373.86	\$ 0.00	\$ 701,803.17
701,803.17	22,450.00	386.22	0.00	724,639.39
724,639.39	22,450.00	398.59	0.00	747,487.98
747,487.98	22,450.00	410.97	0.00	770,348.95
770,348.95	22,450.00	423.35	0.00	793,222.30
793,222.30	22,450.00	435.74	0.00	816,108.04
816,108.04	22,450.00	448.14	0.00	839,006.18
839,006.18	22,450.00	460.54	0.00	861,916.72
861,916.72	22,450.00	472.95	0.00	884,839.67
884,839.67	22,450.00	485.37	0.00	907,775.04
907,775.04	22,450.00	497.79	0.00	930,722.83
930,722.83	22,450.00	490.88	71,400.00	882,263.71
678,979	269,400	5,284	71,400	882,263
Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
\$ 882,263.71	\$ 22,450.00	\$ 481.26	\$ 10,000.00	\$ 895,194.97
895,194.97	22,450.00	490.98	0.00	918,135.95
918,135.95	22,450.00	503.40	0.00	941,089.35
941,089.35	22,450.00	515.84	0.00	964,055.19
964,055.19	22,450.00	528.28	0.00	987,033.47
987,033.47	22,450.00	508.90	117,497.04	892,495.33
892 495 33	22 450 00	489.52	0.00	915,434.85
052,455.55	22,430.00			
915,434.85	22,450.00	501.94	0.00	938,386.79
· ·	•			938,386.79 813,220.66
915,434.85	22,450.00	501.94	0.00	•
915,434.85 938,386.79	22,450.00 22,450.00	501.94 474.27	0.00 148,090.40	813,220.66
915,434.85 938,386.79 813,220.66	22,450.00 22,450.00 22,450.00	501.94 474.27 416.05	0.00 148,090.40 112,722.00	813,220.66 723,364.71
	\$ 678,979.31 701,803.17 724,639.39 747,487.98 770,348.95 793,222.30 816,108.04 839,006.18 861,916.72 884,839.67 907,775.04 930,722.83 678,979 Begining Balance \$ 882,263.71 895,194.97 918,135.95 941,089.35 964,055.19 987,033.47	\$ 678,979.31 \$ 22,450.00 701,803.17 22,450.00 724,639.39 22,450.00 747,487.98 22,450.00 770,348.95 22,450.00 816,108.04 22,450.00 839,006.18 22,450.00 861,916.72 22,450.00 907,775.04 22,450.00 930,722.83 22,450.00 678,979 269,400 Begining Balance \$ 882,263.71 \$ 22,450.00 895,194.97 22,450.00 918,135.95 22,450.00 941,089.35 22,450.00 987,033.47 22,450.00	\$ 678,979.31 \$ 22,450.00 \$ 373.86 701,803.17 22,450.00 386.22 724,639.39 22,450.00 398.59 747,487.98 22,450.00 410.97 770,348.95 22,450.00 423.35 793,222.30 22,450.00 435.74 816,108.04 22,450.00 448.14 839,006.18 22,450.00 460.54 861,916.72 22,450.00 472.95 884,839.67 22,450.00 485.37 907,775.04 22,450.00 497.79 930,722.83 22,450.00 497.79 930,722.83 22,450.00 490.88 678,979 269,400 5,284 Begining Balance Contribution Interest Earned \$ 882,263.71 \$ 22,450.00 \$ 481.26 895,194.97 22,450.00 503.40 941,089.35 22,450.00 515.84 964,055.19 22,450.00 508.90	\$678,979.31 \$22,450.00 \$373.86 \$0.00 701,803.17 22,450.00 386.22 0.00 724,639.39 22,450.00 398.59 0.00 747,487.98 22,450.00 410.97 0.00 770,348.95 22,450.00 423.35 0.00 793,222.30 22,450.00 435.74 0.00 816,108.04 22,450.00 448.14 0.00 839,006.18 22,450.00 460.54 0.00 861,916.72 22,450.00 472.95 0.00 884,839.67 22,450.00 485.37 0.00 907,775.04 22,450.00 497.79 0.00 930,722.83 22,450.00 497.79 0.00 930,722.83 22,450.00 497.79 0.00 930,722.83 22,450.00 490.88 71,400.00 678,979 269,400 5,284 71,400 Begining Balance Contribution Interest Earned Expenditures \$882,263.71 \$22,450.00 \$481.26 \$10,000.00 895,194.97 22,450.00 490.98 0.00 918,135.95 22,450.00 503.40 0.00 941,089.35 22,450.00 515.84 0.00 964,055.19 22,450.00 528.28 0.00

PRN:10/23/2021 Page 86 of 122

Analysis Date - January 1, 2022 Cash Flow - Monthly

2028	Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
January	\$ 769,072.89	\$ 22,450.00	\$ 422.66	\$ 0.00	\$ 791,945.55
February	791,945.55	22,450.00	435.05	0.00	814,830.60
March	814,830.60	22,450.00	447.45	0.00	837,728.05
April	837,728.05	22,450.00	459.85	0.00	860,637.90
May	860,637.90	22,450.00	472.26	0.00	883,560.16
June	883,560.16	22,450.00	482.56	7,826.00	898,666.72
July	898,666.72	22,450.00	492.86	0.00	921,609.58
August	921,609.58	22,450.00	474.41	113,988.00	830,545.99
September	830,545.99	22,450.00	455.96	0.00	853,451.95
October	853,451.95	22,450.00	468.37	0.00	876,370.32
November	876,370.32	22,450.00	480.78	0.00	899,301.10
December	899,301.10	22,450.00	493.20	0.00	922,244.30
	769,072	269,400	5,585	121,814	922,244
2029	Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
January	\$ 922,244.30	\$ 22,450.00	\$ 503.04	\$ 9,550.00	\$ 935,647.34
February	935,647.34	22,450.00	512.89	0.00	958,610.23
March	958,610.23	22,450.00	525.33	0.00	981,585.56
April	981,585.56	22,450.00	537.77	0.00	1,004,573.33
May	1,004,573.33	22,450.00	550.22	0.00	1,027,573.55
June	1,027,573.55	22,450.00	557.27	20,000.00	1,030,580.82
July	1,030,580.82	22,450.00	564.31	0.00	1,053,595.13
August	1,053,595.13	22,450.00	576.78	0.00	1,076,621.91
September	1,076,621.91	22,450.00	525.93	233,800.00	865,797.84
October	865,797.84	22,450.00	475.05	0.00	888,722.89
November	888,722.89	22,450.00	487.47	0.00	911,660.36
December	911,660.36	22,450.00	499.90	0.00	934,610.26
	922,244	269,400	6,315	263,350	934,610

PRN:10/23/2021 Page 87 of 122

Analysis Date - January 1, 2022 Cash Flow - Monthly

2030	Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
January	\$ 934,610.26	\$ 22,450.00	\$ 512.33	\$ 0.00	\$ 957,572.59
February	957,572.59	22,450.00	524.77	0.00	980,547.36
March	980,547.36	22,450.00	537.21	0.00	1,003,534.57
April	1,003,534.57	22,450.00	549.66	0.00	1,026,534.23
May	1,026,534.23	22,450.00	557.28	17,880.00	1,031,661.51
June	1,031,661.51	22,450.00	562.89	7,407.20	1,047,267.20
July	1,047,267.20	22,450.00	481.76	338,184.00	732,014.96
August	732,014.96	22,450.00	402.59	0.00	754,867.55
September	754,867.55	22,450.00	414.97	0.00	777,732.52
October	777,732.52	22,450.00	422.98	16,128.00	784,477.50
November	784,477.50	22,450.00	431.01	0.00	807,358.51
December	807,358.51	22,450.00	443.40	0.00	830,251.91
	934,610	269,400	5,840	379,599	830,251
2031	Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
January	\$ 830,251.91	\$ 22,450.00	\$ 455.80	\$ 0.00	\$ 853,157.71
February	853,157.71	22,450.00	468.21	0.00	876,075.92
March	876,075.92	22,450.00	480.62	0.00	899,006.54
April	899,006.54	22,450.00	493.04	0.00	921,949.58
May	921,949.58	22,450.00	505.47	0.00	944,905.05
June	944,905.05	22,450.00	493.90	88,615.60	879,233.35
July	879,233.35	22,450.00	482.33	0.00	902,165.68
August	902,165.68	22,450.00	494.75	0.00	925,110.43
September	925,110.43	22,450.00	507.18	0.00	948,067.61
October	948,067.61	22,450.00	486.98	120,492.00	850,512.59
November	850,512.59	22,450.00	466.77	0.00	873,429.36
NOVCITIBET	000,011.00	,			
December	873,429.36	22,450.00	479.19	0.00	896,358.55
	·	•	479.19 5,814	209,107	896,358.55 896,358

PRN:10/23/2021 Page 88 of 122

Analysis Date - January 1, 2022 Cash Flow - Monthly

2032	Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
January	\$ 896,358.55	\$ 22,450.00	\$ 487.00	\$ 17,000.00	\$ 902,295.55
February	902,295.55	22,450.00	494.82	0.00	925,240.37
March	925,240.37	22,450.00	507.25	0.00	948,197.62
April	948,197.62	22,450.00	519.69	0.00	971,167.31
May	971,167.31	22,450.00	532.13	0.00	994,149.44
June	994,149.44	22,450.00	544.58	0.00	1,017,144.02
July	1,017,144.02	22,450.00	557.03	0.00	1,040,151.05
August	1,040,151.05	22,450.00	569.50	0.00	1,063,170.55
September	1,063,170.55	22,450.00	581.96	0.00	1,086,202.51
October	1,086,202.51	22,450.00	594.44	0.00	1,109,246.95
November	1,109,246.95	22,450.00	606.92	0.00	1,132,303.87
December	1,132,303.87	22,450.00	619.41	0.00	1,155,373.28
	896,358	269,400	6,614	17,000	1,155,373
2033	Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
January	\$ 1,155,373.28	\$ 22,450.00	\$ 631.91	\$ 0.00	\$ 1,178,455.19
February	1,178,455.19	22,450.00	644.41	0.00	1,201,549.60
March	1,201,549.60	22,450.00	656.92	0.00	1,224,656.52
April	1,224,656.52	22,450.00	669.44	0.00	1,247,775.96
May	1,247,775.96	22,450.00	681.96	0.00	1,270,907.92
June	1,270,907.92	22,450.00	371.26	1,193,447.20	100,281.98
July	100,281.98	22,450.00	60.40	0.00	122,792.38
August	122,792.38	22,450.00	70.25	8,643.60	136,669.03
September	136,669.03	22,450.00	67.20	47,679.10	111,507.13
October	111,507.13	22,450.00	59.17	27,001.00	107,015.30
				0.00	129,529.35
November	107,015.30	22,450.00	64.05	0.00	129,329.33
November December	107,015.30 129,529.35	22,450.00 22,450.00	64.05 76.24	0.00	152,055.59
	·	·			•

PRN:10/23/2021 Page 89 of 122

Analysis Date - January 1, 2022 Cash Flow - Monthly

2034	Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
January	\$ 152,055.59	\$ 22,450.00	\$ 88.44	\$ 0.00	\$ 174,594.03
February	174,594.03	22,450.00	100.65	0.00	197,144.68
March	197,144.68	22,450.00	112.87	0.00	219,707.55
April	219,707.55	22,450.00	125.09	0.00	242,282.64
May	242,282.64	22,450.00	137.32	0.00	264,869.96
June	264,869.96	22,450.00	147.43	7,826.00	279,641.39
July	279,641.39	22,450.00	157.55	0.00	302,248.94
August	302,248.94	22,450.00	163.18	24,435.00	300,427.12
September	300,427.12	22,450.00	168.81	0.00	323,045.93
October	323,045.93	22,450.00	181.06	0.00	345,676.99
November	345,676.99	22,450.00	193.32	0.00	368,320.31
December	368,320.31	22,450.00	205.59	0.00	390,975.90
	152,055	269,400	1,781	32,261	390,975
2035	Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
January	\$ 390,975.90	\$ 22,450.00	\$ 217.86	\$ 0.00	\$ 413,643.76
February	413,643.76	22,450.00	230.14	0.00	436,323.90
March	436,323.90	22,450.00	242.42	0.00	459,016.32
April	459,016.32	22,450.00	254.71	0.00	481,721.03
May	481,721.03	22,450.00	267.01	0.00	504,438.04
June	504,438.04	22,450.00	276.21	11,480.00	515,684.25
July	515,684.25	22,450.00	280.57	17,880.00	520,534.82
August	520,534.82	22,450.00	288.04	0.00	543,272.86
September	543,272.86	22,450.00	300.35	0.00	566,023.21
October	566,023.21	22,450.00	312.68	0.00	588,785.89
November	588,785.89	22,450.00	325.01	0.00	611,560.90
December	611,560.90	22,450.00	337.34	0.00	634,348.24

PRN:10/23/2021 Page 90 of 122

Analysis Date - January 1, 2022 Cash Flow - Monthly

2036	Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
January	\$ 634,348.24	\$ 22,450.00	\$ 349.69	\$ 0.00	\$ 657,147.93
February	657,147.93	22,450.00	362.04	0.00	679,959.97
March	679,959.97	22,450.00	374.39	0.00	702,784.36
April	702,784.36	22,450.00	386.76	0.00	725,621.12
May	725,621.12	22,450.00	399.12	0.00	748,470.24
June	748,470.24	22,450.00	329.96	301,077.75	470,172.45
July	470,172.45	22,450.00	260.76	0.00	492,883.21
August	492,883.21	22,450.00	273.06	0.00	515,606.27
September	515,606.27	22,450.00	285.37	0.00	538,341.64
October	538,341.64	22,450.00	297.68	0.00	561,089.32
November	561,089.32	22,450.00	310.00	0.00	583,849.32
December	583,849.32	22,450.00	322.33	0.00	606,621.65
	634,348	269,400	3,951	301,077	606,621
2037	Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
January	\$ 606,621.65	\$ 22,450.00	\$ 334.67	\$ 0.00	\$ 629,406.32
February	629,406.32	22,450.00	347.01	0.00	652,203.33
March	652,203.33	22,450.00	359.36	0.00	675,012.69
April	675,012.69	22,450.00	371.71	0.00	697,834.40
May	697,834.40	22,450.00	384.07	0.00	720,668.47
June	720,668.47	22,450.00	396.44	0.00	743,514.91
July	743,514.91	22,450.00	317.23	338,184.00	428,098.14
August	428,098.14	22,450.00	231.82	22,680.00	428,099.96
September	428,099.96	22,450.00	192.88	166,467.42	284,275.42
October	284,275.42	22,450.00	160.06	0.00	306,885.48
November	306,885.48	22,450.00	172.31	0.00	329,507.79
December	329,507.79	22,450.00	184.56	0.00	352,142.35
December	329,507.79 606,621	22,450.00 269,400	184.56 3,452	0.00 527,331	352,142.35 352,142

PRN:10/23/2021 Page 91 of 122

Analysis Date - January 1, 2022 Cash Flow - Monthly

2038	Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
January	\$ 352,142.35	\$ 22,450.00	\$ 196.82	\$ 0.00	\$ 374,789.17
February	374,789.17	22,450.00	209.09	0.00	397,448.26
March	397,448.26	22,450.00	221.36	0.00	420,119.62
April	420,119.62	22,450.00	233.65	0.00	442,803.27
May	442,803.27	22,450.00	245.93	0.00	465,499.20
June	465,499.20	22,450.00	258.23	0.00	488,207.43
July	488,207.43	22,450.00	270.53	0.00	510,927.96
August	510,927.96	22,450.00	282.83	0.00	533,660.79
September	533,660.79	22,450.00	295.15	0.00	556,405.94
October	556,405.94	22,450.00	307.47	0.00	579,163.41
November	579,163.41	22,450.00	319.79	0.00	601,933.20
December	601,933.20	22,450.00	332.13	0.00	624,715.33
	352,142	269,400	3,172	0	624,715
2039	Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
January	\$ 624,715.33	\$ 22,450.00	\$ 341.26	\$ 11,855.00	\$ 635,651.59
February	635,651.59	22,450.00	350.39	0.00	658,451.98
March	658,451.98	22,450.00	362.74	0.00	681,264.72
April	681,264.72	22,450.00	375.10	0.00	704,089.82
May	704,089.82	22,450.00	374.93	46,282.50	680,632.25
June	680,632.25	22,450.00	280.07	349,607.00	353,755.32
July	353,755.32	22,450.00	197.70	0.00	376,403.02
August	376,403.02	22,450.00	209.97	0.00	399,062.99
September	399,062.99	22,450.00	222.24	0.00	421,735.23
October	421,735.23	22,450.00	216.71	65,771.75	378,630.19
November	378,630.19	22,450.00	211.17	0.00	401,291.36
December	401,291.36	22,450.00	223.45	0.00	423,964.81
	624,715	269,400	3,365	473,516	423,964

PRN:10/23/2021 Page 92 of 122

Analysis Date - January 1, 2022 Cash Flow - Monthly

2040	Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
January	\$ 423,964.81	\$ 22,450.00	\$ 227.79	\$ 29,316.00	\$ 417,326.60
February	417,326.60	22,450.00	232.13	0.00	440,008.73
March	440,008.73	22,450.00	244.42	0.00	462,703.15
April	462,703.15	22,450.00	256.71	0.00	485,409.86
May	485,409.86	22,450.00	269.01	0.00	508,128.87
June	508,128.87	22,450.00	281.32	0.00	530,860.19
July	530,860.19	22,450.00	293.63	0.00	553,603.82
August	553,603.82	22,450.00	275.08	113,988.00	462,340.90
September	462,340.90	22,450.00	256.51	0.00	485,047.41
October	485,047.41	22,450.00	268.81	0.00	507,766.22
November	507,766.22	22,450.00	281.12	0.00	530,497.34
December	530,497.34	22,450.00	293.43	0.00	553,240.77
	423,964	269,400	3,179	143,304	553,240
2041	Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
January	\$ 553,240.77	\$ 22,450.00	\$ 305.75	\$ 0.00	\$ 575,996.52
February	575,996.52	22,450.00	318.08	0.00	598,764.60
March	598,764.60	22,450.00	330.41	0.00	621,545.01
April	621,545.01	22,450.00	342.75	0.00	644,337.76
May	644,337.76	22,450.00	355.10	0.00	667,142.86
June	667,142.86	22,450.00	341.19	96,950.00	592,984.05
July	592,984.05	22,450.00	316.04	41,500.00	574,250.09
August	574,250.09	22,450.00	317.13	0.00	597,017.22
September	597,017.22	22,450.00	329.46	0.00	619,796.68
September October	597,017.22 619,796.68	22,450.00 22,450.00	329.46 306.91	0.00 128,850.00	619,796.68 513,703.59
•	·	·			•
October	619,796.68	22,450.00	306.91	128,850.00	513,703.59

PRN:10/23/2021 Page 93 of 122

Analysis Date - January 1, 2022 Cash Flow - Monthly

2042	Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
January	\$ 559,184.58	\$ 22,450.00	\$ 304.37	\$ 17,000.00	\$ 564,938.95
February	564,938.95	22,450.00	312.09	0.00	587,701.04
March	587,701.04	22,450.00	324.42	0.00	610,475.46
April	610,475.46	22,450.00	336.75	0.00	633,262.21
May	633,262.21	22,450.00	349.10	0.00	656,061.31
June	656,061.31	22,450.00	359.44	7,407.20	671,463.55
July	671,463.55	22,450.00	369.79	0.00	694,283.34
August	694,283.34	22,450.00	382.15	0.00	717,115.49
September	717,115.49	22,450.00	394.52	0.00	739,960.01
October	739,960.01	22,450.00	406.89	0.00	762,816.90
November	762,816.90	22,450.00	419.27	0.00	785,686.17
December	785,686.17	22,450.00	431.66	0.00	808,567.83
	559,184	269,400	4,390	24,407	808,567
2043	Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
January	\$ 808,567.83	\$ 22,450.00	\$ 441.47	\$ 9,550.00	\$ 821,909.30
February	821,909.30	22,450.00	451.28	0.00	844,810.58
March	844,810.58	22,450.00	463.69	0.00	867,724.27
April	867,724.27	22,450.00	476.10	0.00	890,650.37
May	890,650.37	22,450.00	488.52	0.00	913,588.89
June	913,588.89	22,450.00	493.40	27,826.00	908,706.29
July	908,706.29	22,450.00	498.30	0.00	931,654.59
August	931,654.59	22,450.00	510.73	0.00	954,615.32
September	954,615.32	22,450.00	419.29	383,532.60	593,952.01
October	593,952.01	22,450.00	327.80	0.00	616,729.81
November	616,729.81	22,450.00	340.14	0.00	639,519.95
December	639,519.95	22,450.00	352.49	0.00	662,322.44
	000 567	252 422	F 262	420.000	662 222
	808,567	269,400	5,263	420,908	662,322

PRN:10/23/2021 Page 94 of 122

Analysis Date - January 1, 2022 Cash Flow - Monthly

2044	Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
January	\$ 662,322.44	\$ 22,450.00	\$ 364.84	\$ 0.00	\$ 685,137.28
February	685,137.28	22,450.00	377.20	0.00	707,964.48
March	707,964.48	22,450.00	389.56	0.00	730,804.04
April	730,804.04	22,450.00	401.93	0.00	753,655.97
May	753,655.97	22,450.00	409.47	17,880.00	758,635.44
June	758,635.44	22,450.00	417.01	0.00	781,502.45
July	781,502.45	22,450.00	337.80	338,184.00	466,106.25
August	466,106.25	22,450.00	251.94	24,435.00	464,373.19
September	464,373.19	22,450.00	257.62	0.00	487,080.81
October	487,080.81	22,450.00	191.71	288,772.00	220,950.52
November	220,950.52	22,450.00	125.76	0.00	243,526.28
December	243,526.28	22,450.00	137.99	0.00	266,114.27
	662,322	269,400	3,662	669,271	266,114
2045	Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
January	\$ 266,114.27	\$ 22,450.00	\$ 145.80	\$ 16,352.00	\$ 272,358.07
February	272,358.07	22,450.00	153.61	0.00	294,961.68
March	294,961.68	22,450.00	165.85	0.00	317,577.53
April	317,577.53	22,450.00	178.10	0.00	340,205.63
May	340,205.63	22,450.00	190.36	0.00	362,845.99
June	362,845.99	22,450.00	123.12	293,547.20	91,871.91
July	91,871.91	22,450.00	55.84	0.00	114,377.75
August	114,377.75	22,450.00	68.03	0.00	136,895.78
September	136,895.78	22,450.00	80.23	0.00	159,426.01
October	159,426.01	22,450.00	85.12	27,001.00	154,960.13
November	154,960.13	22,450.00	90.02	0.00	177,500.15
December	177,500.15	22,450.00	102.23	0.00	200,052.38
	200 114	200,400	4 420	225 222	200.052
	266,114	269,400	1,438	336,900	200,05

PRN:10/23/2021 Page 95 of 122

Analysis Date - January 1, 2022 Cash Flow - Monthly

Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
\$ 200,052.38	\$ 22,450.00	\$ 114.44	\$ 0.00	\$ 222,616.82
222,616.82	22,450.00	126.66	0.00	245,193.48
245,193.48	22,450.00	138.89	0.00	267,782.37
267,782.37	22,450.00	151.13	0.00	290,383.50
290,383.50	22,450.00	163.37	0.00	312,996.87
312,996.87	22,450.00	154.11	79,420.00	256,180.98
256,180.98	22,450.00	144.84	0.00	278,775.82
278,775.82	22,450.00	157.08	0.00	301,382.90
301,382.90	22,450.00	169.33	0.00	324,002.23
324,002.23	22,450.00	94.20	322,652.00	23,894.43
23,894.43	22,450.00	19.02	0.00	46,363.45
46,363.45	22,450.00	31.19	0.00	68,844.64
200,052	269,400	1,464	402,072	68,844
Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
\$ 68,844.64	\$ 22,450.00	\$ 40.66	\$ 10,000.00	\$ 81,335.30
81,335.30	22,450.00	50.14	0.00	103,835.44
103,835.44	22,450.00	62.32	0.00	126,347.76
126,347.76	22,450.00	74.52	0.00	148,872.28
148,872.28	22,450.00	86.72	0.00	171,409.00
171,409.00	22,450.00	98.93	0.00	193,957.93
193,957.93	22,450.00	111.14	0.00	216,519.07
216,519.07	22,450.00	123.36	0.00	239,092.43
239,092.43	22,450.00	110.27	93,478.40	168,174.30
168,174.30	22,450.00	97.17	0.00	190,721.47
100,17 1100	,			
190,721.47	22,450.00	109.39	0.00	213,280.86
·	·	109.39 121.61	0.00 0.00	213,280.86 235,852.47
	\$ 200,052.38 222,616.82 245,193.48 267,782.37 290,383.50 312,996.87 256,180.98 278,775.82 301,382.90 324,002.23 23,894.43 46,363.45 200,052 Begining Balance \$ 68,844.64 81,335.30 103,835.44 126,347.76 148,872.28 171,409.00 193,957.93 216,519.07 239,092.43	\$ 200,052.38 \$ 22,450.00	\$ 200,052.38 \$ 22,450.00 \$ 114.44	\$200,052.38 \$22,450.00 \$114.44 \$0.00 222,616.82 22,450.00 126.66 0.00 245,193.48 22,450.00 138.89 0.00 267,782.37 22,450.00 151.13 0.00 290,383.50 22,450.00 154.11 79,420.00 256,180.98 22,450.00 157.08 0.00 312,996.87 22,450.00 157.08 0.00 301,382.90 22,450.00 169.33 0.00 324,002.23 22,450.00 169.33 0.00 324,002.23 22,450.00 19.02 0.00 46,363.45 22,450.00 31.19 0.00 200,052 269,400 17,464 402,072 469,363.45 22,450.00 50.14 0.00 103,835.44 22,450.00 50.14 0.00 126,347.76 22,450.00 50.14 0.00 126,347.76 22,450.00 62.32 0.00 126,347.76 22,450.00 62.32 0.00 126,347.76 22,450.00 74.52 0.00 148,872.28 22,450.00 98.93 0.00 193,957.93 22,450.00 98.93 0.00 193,957.93 22,450.00 123.36 0.00 239,092.43 22,450.00 123.36 0.00 229,450.00 123.36 0.00 229,092.43 22,450.00 123.36 0.00 229,092.43 22,450.00 123.36 0.00 239,092.43 22,450.00 123.36 0.00

PRN:10/23/2021 Page 96 of 122

Analysis Date - January 1, 2022 Cash Flow - Monthly

Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
\$ 235,852.47	\$ 22,450.00	\$ 133.83	\$ 0.00	\$ 258,436.30
258,436.30	22,450.00	146.07	0.00	281,032.37
281,032.37	22,450.00	158.31	0.00	303,640.68
303,640.68	22,450.00	170.55	0.00	326,261.23
326,261.23	22,450.00	182.81	0.00	348,894.04
348,894.04	22,450.00	195.06	0.00	371,539.10
371,539.10	22,450.00	207.33	0.00	394,196.43
394,196.43	22,450.00	217.26	8,643.60	408,220.09
408,220.09	22,450.00	227.20	0.00	430,897.29
430,897.29	22,450.00	239.48	0.00	453,586.77
453,586.77	22,450.00	251.77	0.00	476,288.54
476,288.54	22,450.00	264.07	0.00	499,002.61
235,852	269,400	2,393	8,643	499,002
Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
\$ 499,002.61	\$ 22,450.00	\$ 276.37	\$ 0.00	\$ 521,728.98
521,728.98	22,450.00	288.68	0.00	544,467.66
544,467.66	22,450.00	301.00	0.00	567,218.66
567,218.66	22,450.00	313.32	0.00	589,981.98
589,981.98	22,450.00	325.65	0.00	612,757.63
612,757.63	22,450.00	315.10	84,511.00	551,011.73
551,011.73	22,450.00	299.70	17,880.00	555,881.43
555,881.43	22,450.00	307.18	0.00	578,638.61
578,638.61	22,450.00	319.51	0.00	601,408.12
601,408.12	22,450.00	331.84	0.00	624,189.96
		24440	0.00	646,984.14
624,189.96	22,450.00	344.18	0.00	040,364.14
624,189.96 646,984.14	22,450.00 22,450.00	356.53	0.00	669,790.67
	\$ 235,852.47	\$ 235,852.47	\$ 235,852.47 \$ 22,450.00 \$ 133.83 258,436.30 22,450.00 146.07 281,032.37 22,450.00 158.31 303,640.68 22,450.00 170.55 326,261.23 22,450.00 195.06 371,539.10 22,450.00 207.33 394,196.43 22,450.00 217.26 408,220.09 22,450.00 27.20 430,897.29 22,450.00 239.48 453,586.77 22,450.00 251.77 476,288.54 22,450.00 264.07 235,852 269,400 2,393 Begining Balance Contribution Interest Earned \$ 499,002.61 \$ 22,450.00 \$ 276.37 521,728.98 22,450.00 301.00 567,218.66 22,450.00 313.32 589,981.98 22,450.00 325.65 612,757.63 22,450.00 315.10 551,011.73 22,450.00 299.70 555,881.43 22,450.00 307.18 578,638.61 22,450.00 319.51	\$ 235,852.47 \$ 22,450.00 \$ 133.83 \$ 0.00 \$ 258,436.30 \$ 22,450.00 \$ 146.07 \$ 0.00 \$ 281,032.37 \$ 22,450.00 \$ 158.31 \$ 0.00 \$ 303,640.68 \$ 22,450.00 \$ 170.55 \$ 0.00 \$ 326,261.23 \$ 22,450.00 \$ 195.06 \$ 0.00 \$ 348,894.04 \$ 22,450.00 \$ 195.06 \$ 0.00 \$ 371,539.10 \$ 22,450.00 \$ 207.33 \$ 0.00 \$ 394,196.43 \$ 22,450.00 \$ 217.26 \$ 8,643.60 \$ 408,220.09 \$ 22,450.00 \$ 227.20 \$ 0.00 \$ 430,897.29 \$ 22,450.00 \$ 239.48 \$ 0.00 \$ 453,586.77 \$ 22,450.00 \$ 251.77 \$ 0.00 \$ 476,288.54 \$ 22,450.00 \$ 264.07 \$ 0.00 \$ 235,852 \$ 269,400 \$ 2,393 \$ 8,643 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$

PRN:10/23/2021 Page 97 of 122

Analysis Date - January 1, 2022 Cash Flow - Monthly

2050	Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
January	\$ 669,790.67	\$ 22,450.00	\$ 368.88	\$ 0.00	\$ 692,609.55
February	692,609.55	22,450.00	381.24	0.00	715,440.79
March	715,440.79	22,450.00	393.61	0.00	738,284.40
April	738,284.40	22,450.00	405.98	0.00	761,140.38
May	761,140.38	22,450.00	418.36	0.00	784,008.74
June	784,008.74	22,450.00	425.33	20,000.00	786,884.07
July	786,884.07	22,450.00	432.31	0.00	809,766.38
August	809,766.38	22,450.00	444.70	0.00	832,661.08
September	832,661.08	22,450.00	457.10	0.00	855,568.18
October	855,568.18	22,450.00	469.51	0.00	878,487.69
November	878,487.69	22,450.00	481.93	0.00	901,419.62
December	901,419.62	22,450.00	494.35	0.00	924,363.97
	669,790	269,400	5,173	20,000	924,363
2051	Begining Balance	Contribution	Interest Earned	Expenditures	Ending Balance
January	\$ 924,363.97	\$ 22,450.00	\$ 506.78	\$ 0.00	\$ 947,320.75
February	947,320.75	22,450.00	519.21	0.00	970,289.96
March	970,289.96	22,450.00	531.65	0.00	993,271.61
April	993,271.61	22,450.00	544.10	0.00	1,016,265.71
May	1,016,265.71	22,450.00	556.56	0.00	1,039,272.27
June	1,039,272.27	22,450.00	559.18	36,333.64	1,025,947.81
July	1,025,947.81	22,450.00	311.82	922,994.00	125,715.63
August	125,715.63	22,450.00	74.18	0.00	148,239.81
September	148,239.81	22,450.00	41.29	166,467.42	4,263.68
October	4,263.68	22,450.00	8.39	0.00	26,722.07
November	26,722.07	22,450.00	20.55	0.00	49,192.62
December	49,192.62	22,450.00	13.39	71,400.00	256.01
	924,363	260,400	2.607	4 407 405	25.0
		269,400	3,687	1,197,195	256

PRN:10/23/2021 Page 98 of 122

Analysis Date - January 1, 2022 Cash Flow - Annual

Period	Beginning Balance	Contribution	Interest Earned	Expenditures	Ending Balance
01/22 - 12/22	\$ 700,000.00	\$ 269,400.00	\$ 5,370.28	\$ 20,000.00	\$ 954,770.28
01/23 - 12/23	954,770.28	269,400.00	5,467.00	661,791.22	567,846.06
01/24 - 12/24	567,846.06	269,400.00	4,128.38	313,207.00	528,167.44
01/25 - 12/25	528,167.44	269,400.00	3,764.87	122,353.00	678,979.31
01/26 - 12/26	678,979.31	269,400.00	5,284.40	71,400.00	882,263.71
01/27 - 12/27	882,263.71	269,400.00	5,718.62	388,309.44	769,072.89
01/28 - 12/28	769,072.89	269,400.00	5,585.41	121,814.00	922,244.30
01/29 - 12/29	922,244.30	269,400.00	6,315.96	263,350.00	934,610.26
01/30 - 12/30	934,610.26	269,400.00	5,840.85	379,599.20	830,251.91
01/31 - 12/31	830,251.91	269,400.00	5,814.24	209,107.60	896,358.55
	700,000.00	2,694,000.00	53,290.01	2,550,931.46	896,358.55

Period	Beginning Balance	Contribution	Interest Earned	Expenditures	Ending Balance
01/32 - 12/32	\$ 896,358.55	\$ 269,400.00	\$ 6,614.73	\$ 17,000.00	\$ 1,155,373.28
01/33 - 12/33	1,155,373.28	269,400.00	4,053.21	1,276,770.90	152,055.59
01/34 - 12/34	152,055.59	269,400.00	1,781.31	32,261.00	390,975.90
01/35 - 12/35	390,975.90	269,400.00	3,332.34	29,360.00	634,348.24
01/36 - 12/36	634,348.24	269,400.00	3,951.16	301,077.75	606,621.65
01/37 - 12/37	606,621.65	269,400.00	3,452.12	527,331.42	352,142.35
01/38 - 12/38	352,142.35	269,400.00	3,172.98	0.00	624,715.33
01/39 - 12/39	624,715.33	269,400.00	3,365.73	473,516.25	423,964.81
01/40 - 12/40	423,964.81	269,400.00	3,179.96	143,304.00	553,240.77
01/41 - 12/41	553,240.77	269,400.00	3,843.81	267,300.00	559,184.58
	896,358.55	2,694,000.00	36,747.35	3,067,921.32	559,184.58


PRN:10/23/2021 Page 99 of 122

Analysis Date - January 1, 2022 Cash Flow - Annual

Period	Beginning Balance	Contribution	Interest Earned	Expenditures	Ending Balance
01/42 - 12/42	\$ 559,184.58	\$ 269,400.00	\$ 4,390.45	\$ 24,407.20	\$ 808,567.83
01/43 - 12/43	808,567.83	269,400.00	5,263.21	420,908.60	662,322.44
01/44 - 12/44	662,322.44	269,400.00	3,662.83	669,271.00	266,114.27
01/45 - 12/45	266,114.27	269,400.00	1,438.31	336,900.20	200,052.38
01/46 - 12/46	200,052.38	269,400.00	1,464.26	402,072.00	68,844.64
01/47 - 12/47	68,844.64	269,400.00	1,086.23	103,478.40	235,852.47
01/48 - 12/48	235,852.47	269,400.00	2,393.74	8,643.60	499,002.61
01/49 - 12/49	499,002.61	269,400.00	3,779.06	102,391.00	669,790.67
01/50 - 12/50	669,790.67	269,400.00	5,173.30	20,000.00	924,363.97
01/51 - 12/51	924,363.97	269,400.00	3,687.10	1,197,195.06	256.01
	559,184.58	2,694,000.00	32,338.49	3,285,267.06	256.01

PRN:10/23/2021 Page 100 of 122

Analysis Date - January 1, 2022 Cash Flow - Chart



PRN:10/23/2021 Page 101 of 122

Analysis Date - January 1, 2022 Supplementary Information

on Future Major Repairs and Replacements

	Estimated Remaining Useful Lives	Estimated Current Replacement	2022 Funding	Components of Fund Balance at
	Life YY:MM	Cost	Requirement	12/31/2021
Common Area Interiors				
Admin. Offices Furnishings/Finishes	13:05	\$ 11,480	\$ 630	\$ 610
Billiards Room Furnishings/Finishes	3:00	16,352	647	3,600
Elevator Cab Interiors	19:06	41,500	1,936	262
Fitness Room Flooring	11:07	8,644	538	497
Fitness Room Strength Stations/Equip.	3:00	29,316	1,160	6,454
Guest Suites Furnishings/Finishes	1:08	37,900	3,314	8,067
Guest Suites Restrooms	17:09	17,206	802	488
Hallways Carpeting	1:08	166,467	22,184	31,994
Hallways Furnishings/Finishes	7:08	233,800	15,578	26,680
Lobby/Galleries Furnishings	9:09	94,424	5,872	8,336
Lobby/Galleries Restrooms	17:04	46,283	2,159	1,557
Lobby/Galleries Wall/Door Finishes	9:09	26,068	1,621	2,301
Social Room Bar/Kitchen	1:08	64,999	2,725	15,168
Social Room Carpeting	1:08	9,779	920	2,052
Social Room Furnishings/Finishes	5:09	59,946	3,994	8,911
		864,164	64,080	116,977
Decks & Planter Boxes				
Lawns/Landscaping Waterproofing	11:05	\$ 840,750	\$ 24,509	\$ 136,416
Pavers/Waterproofing	11:05	345,290	10,066	56,025
Planter Boxes Waterproofing	24:09	202,160	6,286	8,924
	_	1,388,200	40,861	201,365

PRN:10/23/2021 Page 102 of 122

Analysis Date - January 1, 2022 Supplementary Information

on Future Major Repairs and Replacements

	Estimated Remaining Useful Lives Life YY:MM	Estimated Current Replacement Cost	2022 Funding Requirement	Components of Fund Balance at 12/31/2021
Engineering Study				
Engineering Study	0:05	\$ 20,000	\$ 2,665	\$ 18,810
	_	20,000	2,665	18,810
Mechanical/Electrical		,	,	,
Domestic Water Pumps/Equipment	17:09	\$ 48,566	\$ 1,888	\$ 3,190
Elevator Mechanical Modernization	29:06	584,810	18,184	2,459
Exhaust/Pressurization Fans	9:05	50,380	1,567	8,719
Fire Alarm System Modernization	23:05	286,140	10,677	4,571
Fire Pump/Equipment	24:05	79,420	1,646	9,164
Garage Gates/Equipment	8:04 -13:06	35,760	2,383	1,987
Generator/Equipment	19:05	96,950	2,261	12,585
Hallways Outside Air Unit	6:07	113,988	8,861	12,979
Video Surveillance System	8:09	16,128	1,368	832
Water Softener System/Equipment	10:00	17,000	1,498	236
		1,329,142	50,333	56,722
Painting & Waterproofing				
Paint Garage Ceilings/Piping	5:08	\$ 34,860	\$ 1,239	\$ 6,895
Paint Garage Walls/Doors	15:07	22,680	1,175	768
Paint Stairway Interiors	1:08	37,055	1,554	8,647
Paint/Waterproof Building Exteriors	1:06	338,184	45,067	67,027
		432,779	49,035	83,337

PRN:10/23/2021 Page 103 of 122

Analysis Date - January 1, 2022 Supplementary Information

on Future Major Repairs and Replacements

	Estimated Remaining Useful Lives Life YY:MM	Estimated Current Replacement Cost	2022 Funding Requirement	Components of Fund Balance at 12/31/2021
Pavement				
Asphalt Paving (Replacement)	5:08	\$ 58,618	\$ 2,083	\$ 11,595
Asphalt Paving (Sealcoat/Rejuvenation)	1:05 -23:05	51,850	5,239	986
Drives/Parking Pavers	5:08	54,612	1,941	10,802
	_	165,080	9,263	23,383
Pool & Spa				
Deck Furniture	11:09	\$ 27,001	\$ 2,099	\$ 142
Decking	5:05	38,828	1,393	7,754
Fencing/Gates	5:05	20,682	742	4,130
Heaters	6:05 -14:05	31,304	1,947	1,623
Interiors Resurfacing	2:07	24,435	1,899	4,837
Summer Kitchen	7:00	9,550	636	1,204
		151,800	8,716	19,690
Railings/Screen Enclosures				
Decktop Railings	9:05	\$ 38,236	\$ 1,189	\$ 6,618
Garage Screen Enclosures	17:05	28,493	1,063	2,180
Units Railings/Screen Enclosures/Doors	17:05	242,307	9,041	18,540
Units Screening Replacement	4:11	71,400	5,328	10,927
		380,436	16,621	38,265

PRN:10/23/2021 Page 104 of 122

Analysis Date - January 1, 2022 Supplementary Information

on Future Major Repairs and Replacements

	Estimated Remaining Useful Lives Life YY:MM	Estimated Current Replacement Cost	2022 Funding Requirement	Components of Fund Balance at 12/31/2021
Roofing				
Mechanical Building Roofing	5:05	\$ 16,273	\$ 584	\$ 3,250
Pool Pavilion Roofing	5:05	10,696	384	2,136
Porte Cochere Roofing	5:05	31,018	1,113	6,194
Tower Roofing (Flat)	2:09	288,772	11,545	64,258
Tower Roofing (Metal Shingle)	14:05	258,019	6,877	38,276
		604,778	20,503	114,114
Site Improvements				
Signage Allowance	5:00	\$ 10,000	\$ 365	\$ 2,030
Site Lighting	3:05	76,685	2,981	16,590
Trellises	5:09	52,776	3,517	7,845
West/Nature Preserve Fencing	17:00	11,855	461	872
		151,316	7,324	27,337
	=	5,487,695	269,401	700,000

PRN:10/23/2021 Page 105 of 122



Analysis Date - January 1, 2022 Component Funding Analysis - Categories

				Estimated		
	Useful	Remaining	12/31/2021	Replacement	Unfunded	
Category	Life	Life	Balance	Cost	Balance	Contribution
Common Area Interiors	10 - 20	1 - 19	\$ 121,021	\$ 864,163	\$ 743,141	\$ 291,191
Decks & Planter Boxes	25	11 - 24	195,116	1,388,200	1,193,083	98,982
Engineering Study	7	0	20,000	20,000	0	0
Mechanical/Electrical	10 - 45	6 - 29	59,972	1,329,142	1,269,170	70,578
Painting & Waterproofing	7 - 20	1 - 15	85,116	432,778	347,661	304,814
Pavement	3 - 25	1 - 23	22,970	165,080	142,110	27,773
Pool & Spa	10 - 25	2 - 14	19,721	151,799	132,077	25,849
Railings/Screen Enclosures	12.5 - 30	4 - 17	38,371	380,435	342,064	33,268
Roofing	20 - 35	2 - 14	110,884	604,778	493,893	138,130
Site Improvements	14 - 24	3 - 17	26,824	151,316	124,491	31,434
		_	700,000	5,487,693	4,787,693	1,022,019

Analysis Date - January 1, 2022

Component Funding Analysis - Items

Category Reserve Item		Remaining Life	12/31/2021 Balance	Estimated Replacement Cost	Unfunded Balance	Contribution
	Useful Life					
Admin. Offices Furnishings/Finishes	17	13	\$ 644	\$ 11,480	\$ 10,835	\$ 834
Billiards Room Furnishings/Finishes	24	3	3,409	16,352	12,942	4,314
Elevator Cab Interiors	20	19	494	41,500	41,005	2,158
Fitness Room Flooring	15	11	549	8,643	8,094	736
Fitness Room Strength Stations/Equip.	24	3	6,112	29,316	23,203	7,734
Guest Suites Furnishings/Finishes	10	1	8,127	37,900	29,772	29,772
Guest Suites Restrooms	20	17	615	17,205	16,590	976
Hallways Carpeting	15	1	34,002	166,467	132,464	132,464
Hallways Furnishings/Finishes	14	7	27,857	233,800	205,942	29,420
Lobby/Galleries Furnishings	15	9	9,001	94,424	85,422	9,491
Lobby/Galleries Restrooms	20	17	1,654	46,282	44,627	2,625
Lobby/Galleries Wall/Door Finishes	15	9	2,484	26,068	23,583	2,620
Social Room Bar/Kitchen	20	1	14,786	64,999	50,212	50,213
Social Room Carpeting	10	1	2,097	9,779	7,681	7,682
Social Room Furnishings/Finishes	14	5	9,183	59,946	50,762	10,152
		_	121,021	864,163	743,141	291,191
Decks & Planter Boxes						
Lawns/Landscaping Waterproofing	25	11	\$ 131,482	\$ 840,750	\$ 709,267	\$ 64,479
Pavers/Waterproofing	25	11	53,999	345,290	291,290	26,481
Planter Boxes Waterproofing	25	24	9,634	202,160	192,525	8,022
			195,116	1,388,200	1,193,083	98,982

The Sorrento at the Colony C.A., Inc.

Analysis Date - January 1, 2022

Component Funding Analysis - Items

				Estimated		
Category	Useful	Remaining	12/31/2021	Replacement	Unfunded	
Reserve Item	Life	Life	Balance	Cost	Balance	Contribution
Engineering Study						
Engineering Study	7	0	\$ 20,000	\$ 20,000	\$0	\$0
		_	20,000	20,000	0	0
Mechanical/Electrical						
Domestic Water Pumps/Equipment	24	17	\$ 3,375	\$ 48,566	\$ 45,191	\$ 2,658
Elevator Mechanical Modernization	30	29	4,645	584,810	580,164	20,006
Exhaust/Pressurization Fans	30	9	8,403	50,380	41,976	4,664
Fire Alarm System Modernization	25	23	5,455	286,140	280,684	12,204
Fire Pump/Equipment	45	24	8,832	79,420	70,587	2,941
Garage Gates/Equipment	14	8 - 13	2,130	35,760	33,629	3,359
Generator/Equipment	40	19	12,129	96,950	84,820	4,464
Hallways Outside Air Unit	12	6	13,581	113,988	100,406	16,734
Video Surveillance System	11	8	1,048	16,128	15,079	1,885
Water Softener System/Equipment	11	10	368	17,000	16,631	1,663
			59,972	1,329,142	1,269,170	70,578
Painting & Waterproofing						
Paint Garage Ceilings/Piping	20	5	\$ 6,709	\$ 34,860	\$ 28,150	\$ 5,630
Paint Garage Walls/Doors	18	15	901	22,680	21,778	1,452
Paint Stairways Interiors	20	1	8,428	37,054	28,625	28,626
Paint/Waterproof Building Exteriors	7	1	69,077	338,184	269,106	269,106
		_	85,116	432,778	347,661	304,814

The Sorrento at the Colony C.A., Inc.

Analysis Date - January 1, 2022

Component Funding Analysis - Items


				Estimated		
Category	Useful	Remaining	12/31/2021	Replacement	Unfunded	
Reserve Item	Life	Life	Balance	Cost	Balance	Contribution
Pavement						
Asphalt Paving (Replacement)	20	5	\$ 11,282	\$ 58,618	\$ 47,335	\$ 9,467
Asphalt Paving (Sealcoat/Rejuvenation)	3	1 - 23	1,177	51,850	50,673	9,486
Drives/Parking Pavers	25	5	10,510	54,612	44,101	8,820
		_	22,970	165,080	142,110	27,773
Pool & Spa						
Deck Furniture	12	11	\$ 536	\$ 27,001	\$ 26,464	\$ 2,406
Decking	25	5	7,473	38,827	31,354	6,271
Fencing/Gates	25	5	3,980	20,681	16,701	3,340
Heaters	15	6 - 14	1,741	31,304	29,562	2,839
Interiors Resurfacing	12	2	4,853	24,435	19,581	9,791
Summer Kitchen	14	7	1,137	9,550	8,412	1,202
			19,721	151,799	132,077	25,849
Railings/Screen Enclosures						
Decktop Railings	30	9	\$ 6,377	\$ 38,235	\$ 31,857	\$ 3,540
Garage Screen Enclosures	25	17	2,172	28,492	26,320	1,548
Units Railings/Screen Enclosures/Doors	25	17	18,477	242,307	223,829	13,166
Units Screening Replacement	12.5	4	11,343	71,400	60,056	15,014
			38,371	380,435	342,064	33,268
Roofing						
Mechanical Building Roofing	26	5	\$ 3,132	\$ 16,273	\$ 13,140	\$ 2,628
Pool Pavilion Roofing	26	5	2,059	10,696	8,636	1,727
Porte Cochere Roofing	26	5	5,970	31,018	25,048	5,010
Tower Roofing (Flat)	23	2	62,831	288,772	225,940	112,970
Tower Roofing (Metal Shingle)	35	14	36,891	258,018	221,126	15,795

The Sorrento at the Colony C.A., Inc.

Analysis Date - January 1, 2022 Component Funding Analysis - Items

				Estimated		
Category Reserve Item	Useful Life	Remaining Life	12/31/2021 Balance	Replacement Cost	Unfunded Balance	Contribution
Site Improvements						
Signage Allowance	26	5	\$ 1,925	\$ 10,000	\$ 8,074	\$ 1,615
Site Lighting	24	3	15,990	76,685	60,694	20,232
Trellises	14	5	8,084	52,776	44,691	8,938
West/Nature Preserve Fencing	24	17	824	11,855	11,030	649
		_	26,824	151,316	124,491	31,434
		_	700,000	5,487,693	4,787,693	1,022,019

PRN:10/23/2021 Page 111 of 122



Chapter 718 & 719 Florida Statutes

The Condominium Act, 1995 The Cooperative Act, 1997

CONDOMINIUMS 718.112 (2)(f) 2 & 3 **COOPERATIVES** 719.106 (1)(j) 2 & 3

- 2. In addition to annual operating expenses, the budget shall include reserve accounts for capital expenditures and deferred maintenance. These accounts shall include, but are not limited to, roof replacement, building painting, and pavement resurfacing, regardless of the amount of deferred maintenance expense or replacement cost, and for any other item for which the deferred maintenance expense or replacement cost exceeds \$10,000. The amount to be reserved shall be computed by means of a formula which is based upon estimated remaining useful life and estimated replacement cost or deferred maintenance expense of each reserve item. The association may adjust replacement reserve assessments annually to take into account any changes in estimates or extension of the useful life of a reserve item caused by deferred maintenance. This subsection does not apply to budgets in which the members of an association have, by a majority vote at a duly called meeting of the association, determined for a fiscal year to provide no reserves or reserves less adequate than required by this subsection. However, prior to turnover of control of an association by a developer to unit owners other than a developer pursuant to s. 718.301, the developer may vote to waive the reserves or reduce the funding of reserves for the first 2 years of the operation of the association, after which time reserves may only be waived or reduced upon the vote of a majority of all nondeveloper voting interests voting in person or by limited proxy at a duly called meeting of the association. If a meeting of the unit owners has been called to determine to provide no reserves or reserves less adequate than required, and such result is not attained or a quorum is not attained, the reserves as included in the budget shall go into effect.
- 3. Reserve funds and any interest accruing thereon shall remain in the reserve account or accounts, and shall be used only for authorized reserve expenditures unless their use for other purposes is approved in advance by a vote of the majority of the voting interests, voting in person or by limited proxy at a duly called meeting of the association. Prior to turnover of control of an association by a developer to unit owners other than the developer pursuant to s 718.301, the developer-controlled association shall not vote to use reserves for purposes other than that

for which they were intended without the approval of a majority of all nondeveloper voting interests,

voting in person or by limited proxy at a duly called meeting of the association.

Florida Administrative Code Reserve Requirements

61B-22.001 Definitions. For the purposes of this chapter, the following definitions shall apply:

- (2) "Capital expenditure" means an expenditure of funds for the purchase of an asset whose life is greater than one year in length, or the replacement of an asset whose life is greater than one year in length, or the addition to an asset which extends the life of the previously existing asset for a period greater than one year.
- (3) "Deferred maintenance" means any maintenance or repair that will be performed less frequently than yearly and will result in maintaining the life of an asset; and
- (4) "Reserves" means any funds which are restricted for deferred maintenance and capital expenditures, including the items required by section 718.112(2)(f)2, Florida Statutes, and any other funds restricted as to use by the condominium documents or the condominium association. "Contingency reserves" which are not restricted as to use by the condominium documents or by the association shall not be considered reserves within the meaning of this rule.

61B-22.003 Budgets. Required elements for estimated operating budgets. The budget for each association shall:

- (d) Include all estimated common expenses or expenditures of the association including the categories set forth in section 718.504(20)(c), Florida Statutes. Reserves for capital expenditures and deferred maintenance required by section 718.112(2)(f), Florida Statutes, must be included in the proposed annual budget and shall not be waived or reduced prior to the mailing to unit owners of a proposed annual budget. If the estimated common expense for any category set forth in the statute is not applicable, the category shall be listed followed by an indication that the expense is not applicable;
- (e) Include a schedule stating each reserve account for capital expenditures and deferred maintenance as a separate line item with the following minimum disclosures;
 - 1. The total estimated useful life of the asset:
 - 2. The estimated remaining useful life of the asset;
 - 3. The estimated replacement cost or deferred maintenance expense of the asset;
 - 4. The estimated fund balance as of the beginning of the period for which the budget will be in effect; and,
 - 5. The developer's total funding obligation, when all units are sold, for each converter reserve account established pursuant to section 718.618, Florida Statutes, if applicable.
- (f) Include a separate schedule of any other reserve funds to be restricted by the association as a separate line item with the following minimum disclosures;
 - 1. The intended use of the restricted funds; and
 - 2. The estimated fund balance of the item as of the beginning of the period for which the budget will be in effect.
- (g) "Contingency reserves" and any other categories of expense which are not restricted as to use shall be stated in the operating portion of the budget rather than the reserve portion of the budget.

61B-22.005 Reserves. Reserves required by statute. Reserves required by section 718.112(2)(f), Florida Statutes, for capital expenditures and deferred maintenance including roofing, painting, paving, and any other item for which the deferred maintenance expense or replacement cost of an item exceeds \$10,000 shall be included in the budget. For the purpose of determining whether the deferred maintenance expense or replacement cost of an item exceeds \$10,000, the association may consider each asset of the association separately. Alternatively, the replacement cost of an item exceeds \$10,000, the association may group similar or related assets together. For example, an association responsible for the maintenance of two swimming pools, each of which will separately require \$6,000 of total deferred maintenance, may establish a pool reserve, but is not required to do so.

61B-22.0051 Estimating Reserve Requirements.

- (1) Formula for calculation of reserves required by statute. Reserves for deferred maintenance and capital expenditures required by section 718.112(2)(f), Florida Statutes, shall be calculated using a formula which will provide funds equal to the total estimated deferred maintenance expense or total estimated replacement cost for an asset over the remaining useful life of the asset. The formula shall provide funds in annual increments and may be adjusted each year for changes in estimates. The formula may consider such factors as inflation and interest or other earnings rates, but must include the following:
 - (a) The estimated remaining useful life of the asset;
 - (b) The estimated deferred maintenance expense or estimated replacement cost of the asset; and,
 - (c) The estimated fund balance of the reserve account as of the beginning of the period for which the budget will be in effect.
- (2) Estimating reserves which are not required by statute. Reserves which are not required by section 718.112(2)(f), Florida Statutes, are not required to be based on any specific formula.
- (3) Estimating reserves when the developer is funding converted reserves. For the purpose of estimating non-converter reserves the estimated fund balance of the non-converter reserve account related to any asset for which the developer has established converter reserves pursuant to section 718.618, Florida Statutes, shall be the sum of:
 - (a) The developer's total funding obligation, when all units are sold, for the converter reserve account pursuant to section 718.618, Florida Statutes,; and,
 - (b) The estimated fund balance of the non-converter reserve account, excluding the developer's converter obligation, as of the beginning of the period for which the budget will be in effect.

61B-22.0052 Funding Requirements and Restrictions on Use.

- (1) Timely funding. Reserves included in the adopted budget are common expenses and must be fully funded unless properly waived or reduced. Reserves shall be funded in at least the same frequency that assessments are due from the unit owners (e.g., monthly or quarterly).
- (2) Restrictions on use. Reserves required by section 718.112(2)(f), Florida Statutes, and other reserves included on the adopted budget, shall only be used for the purposes for

which they were intended unless their use for other purposes is approved in advance by the unit owners according to section 718.112(2)(f)3, Florida Statutes. In a multi-condominium association, the same procedures which are specified for the waiving or reduction of reserves shall apply where an association seeks to use reserve funds for purposes other than which the funds were originally reserved. Expenditure of unallocated interest income earned on reserve funds is restricted to any of the capital expenditures, deferred maintenance or other items for which reserve accounts have been established.

61B-22.0053 Waiver of Reserves.

- (1) Annual vote required to waive reserves. Any vote to waive or reduce reserves for capital expenditures and deferred maintenance required by section 718.112(2)(f)2, Florida Statutes, shall be effective for only one annual budget, and the vote must be taken annually. Additionally, in a multi-condominium association, no waiver or reduction is effective as to a particular condominium unless conducted at a meeting at which a majority of the voting interests in that condominium are present, in person or by proxy, and a majority of those present in person or by limited proxy vote to waive or reduce reserves.
- (2) Developer voting restrictions. Prior to turnover, the developer may cast votes to waive or reduce reserves during the first two fiscal years only, beginning with the date of the recording of the declaration. In the case of a multi-condominium association, this restriction applies to the association's first two fiscal years beginning with the recording of the initial declaration.

1.

2. 61B-22.006 Financial Reporting Requirements.

- (3) Disclosure requirements. The financial statements required by sections 718.111(14) and 718.301(4), Florida Statutes, shall contain the following disclosures within the financial statements, notes, or supplementary information:
 - (a) The following reserve disclosures shall be made regardless of whether reserves have been waived for the fiscal period covered by the financial statements:
 - 1. The beginning balance in each reserve account as of the beginning of the fiscal period covered by the financial statements;
 - 2. The amount of assessments and other additions to each reserve account, including authorized transfers from other reserve accounts:
 - 3. The amount expended or removed from each reserve account, including authorized transfers to other reserve accounts;
 - 4. The ending balance in each reserve account as of the end of the fiscal period covered by the financial statements:
 - 5. The manner by which reserve items were estimated, the date the estimates were last made, the association's policies for allocating reserve fund interest, and whether reserves have been waived during the period covered by the financial statements; and,
 - 6. If the developer has established converter reserves pursuant to section 718.618(1), Florida Statutes, each converter reserve account shall be identified and include the disclosures required by this rule.

<u>Chapter 61B – 22, Florida Administrative Code</u> <u>Summary of Rule Amendments</u>

61B-22.003 Budgets

- Recognizes the use of a pooled account for reserves and provides that a schedule showing each reserve account is not necessary if a pooled account for reserves is used.
- Provides an alternate disclosure method for the use of a pooled account for reserves.

61B-22.005 Reserves

- Recognizes the concept of funding a group of assets using a pooled analysis of two or more required assets and provides requirements and direction related to the pooled account method.
- Clarifies that the chosen reserve funding formula shall not include any type of balloon payment.

Amended Rule Text

61B – 22.003 Budgets

- (e) Unless the association maintains a pooled account for reserves required by Section 718.112(2)(f)2., Florida Statutes, the association shall include a schedule stating each reserve account for capital expenditures and deferred maintenance as a separate line item with the following minimum disclosures:
- (f) If the association maintains a pooled account for reserves required by Section 718.112(2)(f)2., Florida Statutes, the association shall include a separate schedule of any pooled reserves with the following minimum disclosures:
 - 1. The total estimated useful life of each asset within the pooled analysis;
 - 2. The estimated remaining useful life of each asset within the pooled analysis;
 - 3. The estimated replacement cost or deferred maintenance expense of each asset within the pooled analysis; and
 - 4. The estimated fund balance of the pooled reserve account as of the beginning of the period for which the budget will be in effect.
 - (g) Include a separate schedule of any other reserve funds to be restricted by the association as a separate line item with the following minimum disclosures:
 - 1. The intended use of the restricted funds; and
 - 2. The estimated fund balance of the item as of the beginning of the period for which the budget will be in effect.

61B - 22.005 Reserves

1) Reserves required by statute. Reserves required by Section 718.112(2)(f), Florida Statutes, for capital expenditures and deferred maintenance including roofing, painting, paving, and any other item for which the deferred maintenance expense or replacement cost exceeds \$10,000 shall be included in the budget. For the purpose of determining whether the deferred maintenance expense or replacement cost of an item exceeds \$10,000, the association may consider each asset of the association separately. Alternatively, the association may group similar or related assets together. For example, an association responsible for the maintenance of two swimming pools,

- each of which will separately require \$6,000 of total deferred maintenance, may establish a pool reserve, but it is not required to do so.
- 2) Commingling operating and reserve funds. Associations that collect operating and reserve assessments as a single payment shall not be considered to have commingled the funds provided the reserve portion of the payment is transferred to a separate reserve account, or accounts, within 30 calendar days from the date such funds were deposited.
- 3) Calculating reserves required by statute. Reserves for deferred maintenance and capital expenditures required by Section 718.112(2)(f), Florida Statutes, shall be calculated using a formula that will provide funds equal to the total estimated deferred maintenance expense or total estimated replacement cost of an asset or group of assets over the remaining useful life of the asset or group of assets. Funding formulas for reserves required by Section 718.112(2)(f), Florida Statutes, shall be based on either a separate analysis of each of the required assets or a pooled analysis of two or more of the required assets.
 - (a) If the association maintains separate reserve accounts for each of the required assets, the amount of the current year contribution to each reserve account shall be the sum of the following two calculations:
 - 1. The total amount necessary, if any, to bring a negative account balance to \$0; and
 - 2. The total estimated deferred maintenance expense or estimated replacement cost of the reserve asset less the estimated balance of the reserve account as of the beginning of the period for which the budget will be in effect. The remainder, if greater than zero, shall be divided by the estimated remaining useful life of the asset. The formula may be adjusted each year for changes in estimates and deferred maintenance performed during the year and may consider factors such as inflation and earnings on invested funds.
 - (b) If the association maintains a pooled account of two or more of the required reserve assets, the amount of contribution to the pooled reserve account as disclosed on the proposed budget shall be not less than that required to ensure that the balance on hand at the beginning of the period for which the budget will go into effect plus the projected annual cash inflows over the remaining estimated useful lives of all of the assets that make up the reserve pool are equal to or greater than the projected annual cash outflows over the remaining estimated useful lives of all of the assets that make up the reserve pool, based on the current reserve analysis. The projected annual cash inflows may include estimated earnings from investment of principal. The reserve funding formula shall not include any type of balloon payment.

TERMS AND DEFINITIONS

ACCRUED FUND BALANCE (AFB): Total Accrued Depreciation. An indicator against which Actual (or projected) Reserve balance can be compared. The Reserve balance that is in direct proportion to the fraction of life "used up" of the current Repair or Replacement cost. This number is calculated for each component, then summed together for an association tool. Two formulae can be utilized, depending on the provider's sensitivity to interest and inflation effects. Note: both yield identical results when interest and inflation are equivalent.

AFB = Current Cost X Effective Age/Useful Life

or

AFB = (Current Cost X Effective Age/Useful Life) + [(Current Cost X Effective Age/Useful Life)/(1 + Interest Rate) ^ Remaining Life] – [(Current Cost X Effective Age/Useful Life) /(1 + Inflation Rate) ^ Remaining Life]

<u>CASH FLOW METHOD:</u> A method of calculating Reserve Funding Plan where contributions to the Reserve fund are designed to offset the variable annual expenditures from the Reserve fund. Different Reserve Funding Plans are tested against the anticipated schedule of Reserve expenses until the desired Funding Goal is achieved. "Because we use the cash flow method, we compute individual line item contributions after the total contribution rate has been established." See "Component Method".

<u>CAPITAL EXPENDITURES</u>: A capital expenditure means any expenditure of funds for: (1) the purchase or replacement of an asset whose useful life is greater than one year, or (2) the addition to an asset that extends the useful life of the previously existing asset for a period greater than one year.

<u>COMPONENT:</u> The individual line items in the Reserve Study, developed or updated in the Physical Analysis. These elements form the building blocks for the Reserve Study. Components typically are: 1) Association responsibility, 2) with limited Useful Life expectancies, 3) predictable Remaining Useful Life expectancies, and 4) above a minimum threshold cost, and 5) as required by local codes. "We have 17 components in our reserve Study."

<u>COMPONENT ASSESSMENT AND VALUATION:</u> The task of estimating Useful Life, Remaining Useful Life, and Repair or Replacement Costs for the Reserve components. This task is accomplished either with or without an on-site inspection, based on Level or Service selected by the client.

<u>COMPONENT FULL FUNDING:</u> When the actual (or projected) cumulative Reserve balance for all components is equal to the Fully Funded Balance.

<u>COMPONENT INVENTORY:</u> The task of selecting and quantifying Reserve Components. This task is accomplished through an on-site inspection, review of association design and organizational documents, and a review of established association precedents, and discussion with appropriate association representative(s).

<u>COMPONENT METHOD</u>: A method of developing a Reserve Funding Plan where the total contribution is based on the sum of contributions for individual components. "Since we calculate a Reserve contribution rate for each component and then sum them all together, we are using the component method to calculate our Reserve contributions." See "Cash Flow Method".



<u>CONDITION ASSESSMENT:</u> The task of evaluating the current condition of the component based on observed and reported characteristics.

CURRENT REPLACEMENT COST: See "Replacement Cost".

<u>DEFERRED MAINTENANCE:</u> Deferred maintenance means any maintenance or repair that: (1) will be performed less frequently than yearly, and (2) will result in maintaining the useful life of an asset.

<u>DEFICIT:</u> An actual (or projected) Reserve Balance less than the Fully Funded Balance. The opposite would be a Surplus.

EFFECTIVE AGE: The difference between Useful Life and Remaining Useful Life. Not always equivalent to chronological age, since some components age irregularly. Used primarily in computations.

<u>FINANCIAL ANALYSIS:</u> The portion of a Reserve Study where current status of the Reserves (measured as cash or Percent Funded) and a recommended Reserve contribution rate (Reserve Funding Plan) are derived, and the projected Reserve income and expense over time is presented. The Financial Analysis is one of the two parts of a Reserve Study.

<u>FULLY FUNDED:</u> When the budget is provided to the owners, it will show the amount of money that must be deposited that year for each reserve item to ensure that, when the time comes, sufficient funds will be available for deferred maintenance or a capital expenditure. (Definition published in "Budgets & Reserve Schedules Made Easy" training manual by the State of Florida Department of Business and Professional Regulations in January 1997).

<u>FUND STATUS:</u> The status of the reserve fund as compared to an established benchmark such as percent funding.

<u>FUNDING PLAN</u>: An association's plan to provide income to a Reserve fund to offset anticipated expenditures from that fund.

FUNDING PRINCIPLES:

- Sufficient Funds When Required
- Stable Contribution Rate over the Years
- Evenly Distributed Contributions over the Years
- Fiscally Responsible

<u>FUNDING GOALS</u>: Independent of methodology utilized, the following represent the basic categories of Funding Plan goals:

- **Baseline Funding** Establishing a Reserve funding goal of keeping the Reserve cash balance above zero.
- **Component Full Funding** Setting a Reserve funding goal of attaining and maintaining cumulative Reserves at or near 100%.



- **Statutory Funding** Establishing a Reserve funding goal of setting aside the specific minimum mount of Reserves of component required by local statutes.
- Threshold Funding Establishing a Reserve funding goal of keeping the Reserve balance above a specified dollar or Percent Funded amount. Depending on the threshold, this may be more or less conservative than "Component Full Funding."

<u>LIFE AND VALUATION ESTIMATES:</u> The task of estimating Useful Life, Remaining Useful Life, and Repair or Replacement Costs for the Reserve Components.

PERCENT FUNDED: The ratio, at a particular point of time (typically the beginning of the Fiscal Year), of the *actual* (or *projected*) Reserve Balance to the accrued *Fund Balance*, expressed as a percentage. "With \$76,000 in Reserves, and since our 100% Funded Balance is \$100,000, our association is 76% Funded".

Editor's Note: since funds can typically be allocated from one component to another with ease, this parameter has no real meaning on an individual Component basis. The purpose of this parameter is to identify the relative strength or weakness of the entire Reserve fund as of a particular point in time. The value of this parameter is in providing a more stable measure of Reserve Fund strength, since cash in Reserves may mean very different things to different associations.

<u>PHYSICAL ANALYSIS:</u> The portion of the Reserve Study where the Component Inventory, Condition Assessment, and Life and Valuation Estimate tasks are performed. This represents one of the two parts of the Reserve Study.

REMAINING USEFUL LIFE (RUL): Also referred to as "Remaining Life" (RL). The estimated time, in years, that a reserve component can be expected to *continue* to serve its intended function. Projects anticipated to occur in the initial year have "zero" Remaining Useful Life.

REPLACEMENT COST: The cost of replacing, repairing, or restoring a Reserve Component to its original functional condition. The Current Replacement Cost would be the cost to replace, repair, or restore the component during that particular year.

RESERVE BALANCE: Actual or projected funds as of a particular point in time that the association has identified for use to defray to the future repair of replacement of those major components which the association is obligated to maintain. Also known as Reserves, Reserve Accounts, Cash Reserves. Based on information provided and not audited

RESERVE PROVIDER: An individual that prepares Reserve Studies.

RESERVE STUDY: A budget planning tool which identifies the current status of the Reserve fund and a stable and equitable Funding Plan to offset the anticipated future major common area expenditures." The Reserve Study consists of two parts: the Physical Analysis and the Financial Analysis. "Our budget and finance committee is soliciting proposals to update our Reserve Study for the next year's budget."

RESPONSIBLE CHARGE: A reserve specialist in responsible charge of a reserve study shall render regular and effective supervision to those individuals performing services which directly and materially affect the quality and competence rendered by the reserve specialist. A reserve specialist shall maintain



such records as are reasonably necessary to establish that the reserve specialist exercised regular and effective supervision of a reserve duty of which he was in responsible charge. A reserve specialist engaged in any of the following acts or practices shall be deemed not to have rendered the regular and effective supervision required herein:

- 1. The regular and continuous absence from principal office premises from which professional services are rendered; expect for performance of field work or presence in a field office maintained exclusively for a specific project:
- 2. The failure to personally inspect or review the work of subordinates where necessary and appropriate;
- 3. The rendering of a limited, cursory or perfunctory review of plans or projects in lieu of an appropriate detailed review;
- 4. The failure to personally be available on a reasonable basis or with adequate advanced notice for consultation and inspection where circumstances require personal availability.

SPECIAL ASSESSMENT: An assessment levied on the members of an association in addition to regular assessments. Special Assessments are often regulated by Governing Documents or local statutes. "Since we need a new roof and there wasn't enough money in the Reserve fund, we had to pass a special assessment."

SURPLUS: An actual (or projected) Reserve Balance greater than the Fully Funded Balances. See Deficit".

<u>USEFUL LIFE (UL):</u> Total Useful Life or Depreciable Life. The estimated time, in years, that a reserve component can be expected to serve its intended function if properly constructed in its present application or installation.

